



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-5178 FAX: (505) 334-5170
[http://emmrds.state.nm.us/ocd/District III/3district.htm](http://emmrds.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

JUL 29 2013

(submit 1 copy to above address)

Date of Test 7-18-2013 Operator BMG API #30-0 39-82251

Property Name EPCMU D-9 Well No. 28 Location: Unit D Section 9 Township 26N Range 1E

Well Status (Shut-In or Producing) Initial PSI: Tubing 65 Intermediate Casing 21 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>21</u>		
10 min	<u>0</u>		<u>21</u>		
15 min	<u>0</u>		<u>21</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	<u>NO</u>	
Surges	<u>NO</u>	
Down to Nothing	<u>yes</u>	
Nothing	<u>yes</u>	
Gas	<u>NO</u>	
Gas & Water	<u>NO</u>	
Water	<u>NO</u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS: Bradenhead Dead for 15 min test

By Bennie Velasquez
Lease operator
(Position)

Witness

E-mail address