



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District3/district3.htm

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

SEP 19 2013

Date of Test SEPT 12, 2013 Operator Parko Inc. API #30-0 43-20675

Property Name LU-LU Well No. 3 Location: Unit N Section 20 Township 23 Range 6W

Well Status (Shut-In or Producing) Tubing 50 Intermediate Casing 220 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes			<u>220</u>	Steady Flow <u>✓</u>	
10 minutes			<u>220</u>	Surges <u> </u>	
15 minutes			<u>220</u>	Down to Nothing <u> </u>	
20 minutes			<u>220</u>	Nothing <u> </u>	
25 minutes				Gas <u>✓</u>	
30 minutes				Gas & Water <u> </u>	
				Water <u> </u>	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD ✓ INTERMEDIATE

REMARKS:

BRADENHEAD HAS STEADY FLOW DOSE NOT
BLOW DOWN, (CONTINUES TO BLOW)
PUMPING UNIT WELL SHUT IN 24 HRS

By Johnny Aragon
Pumper
(Position)

Witness

E-mail address Oragon_Johnny@yahoo.com