## ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

OIL CONS. DIV DIST. 3

## BRADENHEAD TEST REPORT

(submit 2 copies to above address)

JUL 1 5 2013

Date of Test $5-25$	-/3 Operator_	NM&O Operating Co. API #30-0 39233	6700S2
Property Name Gavilan Well No. 2 Location: Unit J Section 26 Township 25N Range 2W			
Well Status (Shut-In or Producing) Tubing 77 Intermediate /UH Casing 77 Bradenhead O			
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH			
TIME INTERNED		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	77	Steady Flow	$\overline{}$
10 minutes O	77	Surges	
15 minutes O	77	Down to Nothing	
20 minutes		Nothing X	
25 minutes		Gas	
30 minutes		Gas & Water	
		Water	
If bradenhead flowed water, check all of the descriptions that apply below:			
CLEAR FRESH SALTY SULFUR BLACK			
5 MINUTE SHUT-IN BRADENHEAD O INTERMEDIATE WH			
Though 1/4" well shot in			
By Carry Davis Witness Jord V. Kelly  (Position)			