

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm



## **BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 6 - 21-13 Operator Elm Ridge Exploration CO LLC API #30-043-20634								
Property Name <u>AXI Apache P</u> Well No. <u>005</u> Location: Unit <u>F</u> Section <u>20</u> Township <u>23N</u> Range <u>04W</u>								
Well Status(Shut-In or Producing) Initial PSI: Tubing 56 Intermediate Casing 75 Bradenhead 0								
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH								
Testing	BH Int Csg Int Csg					FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE		
TIME 5 min	0	WA	75		<u> </u>	Steady Flow		
10 min_	0	N/n	75		_			
15 min_	0	n/n	75		_	Down to Nothing ,		OIL CONS. DIV DIST. 3
20 min_	0	No	75		_	Nothing		JUL 0 8 2013
25 min_	0	rip	75		_	Gas		
30 min_	0	NA	75			Gas & Water		
						Water		
If bradenhead flowed water, check all of the descriptions that apply below:								
	CLEAR FRESH SALTY					SULFUR	BLACK	
SMINUTE SHUT-IN PRESSURE BRADENHEAD O INTERMEDIATE / /A  REMARKS: O ON Braden Head								
By Eji Mantinez Witness  (Position)  E-mail address								
E-mail address								