



& NATURAL RESOURCES DEPARTMENT

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

OIL CONS. DIV DIST. 3


Date of Test 6-4-13 Operator NM&O Operating Co. API #30-0392323100S1

JUL 15 2013

Property Name Rucker Lake Well No. 2SWD Location: Unit K Section 24 Township 25N Range 2W

Well Status (Shut-In or Producing) Tubing 10.5 Intermediate X Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	<u>B-H</u>	INTERMEDIATE	CASING		
5 minutes	<u>0</u>		<u>0</u>	Steady Flow	
10 minutes	<u>0</u>		<u>0</u>	Surges	
15 minutes	<u>0</u>		<u>0</u>	Down to Nothing	
20 minutes				Nothing <u>X</u>	
25 minutes				Gas	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE 1/4

REMARKS:

Thigh 1/4"

By Craig Davis

Witness Jeffrey Kelly

(Position)

JUL 8 2013