

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT



OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT (submit 1 copy to above address)

JUN 27 2013

Date of Test 6-5-2013 Operator Elm Ridge Exploration CO LLC API #30-039-05088

Property Name_AXI Apache A__Well No.__003_Location: Unit_M_Section_10_Township_23N_Range_05W Well Status(Shut-In or Producing) Initial PSI: Tubing_18__Intermediate <u>NA__</u>Casing_18__Bradenhead____

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE						FLOW CHARACTERISTICS		
Testing		Bradenh		INTERM		BRADENHEAD INTERMEDIATE		
TIME 5 min	<u>BH</u>	Int	Csg 18	Int	Csg	Steady Flow		
10 min_	0		18			Surges		
15 min_	_0		18			Down to Nothing	OIL CONS. DIV DIST. 3	
20 min_	0_		18			Nothing V	JUN 27 2013	
25 min_	0		18			Gas		
30 min_	0		18			Gas & Water		
						Water		
If bradenhead flowed water, check all of the descriptions that apply below:								
	CLEAF	R	FRESH	S	SALTY	SULFURBLACK		
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE								
REMARKS: Well is Logged off AND shut in - DOWNSTREAM line leak								
By Joe J-Rowert J- Witness_ <u>AUMPER</u> (Position)						/itness		
E-mail address								