



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 06-25-13 Operator Elm Ridge Exploration CO LLC API #30-039-24558

Property Name Lybrook 19 Well No. 002R Location: Unit K Section 19 Township 24N Range 06W
Well Status(Shut-In or Producing) Initial PSI: Tubing 50 Intermediate Casing 67 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>67</u>		
10 min					
15 min					
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing		<u>Nothing</u>
Gas		
Gas & Water		
Water		

OIL CONS. DIV DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

JUL 08 2013

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

Gauge on 5 min Nothing

By Oscar Perreya
Pumper
(Position)

Witness

E-mail address