

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company: BP America Production Company	Contact: Courtney Cochran
Address: 200 Energy Ct. Farmington, NM 87401	Telephone No.: 505-326-9457
Facility Name: GCU Com B 143E	Facility Type: Natural Gas Well

Surface Owner: FEE	Mineral Owner: FEE	API No.: 3004524284
--------------------	--------------------	---------------------

**LOCATION OF RELEASE**

Unit Letter M	Section 25	Township 29N	Range 12W	Feet from the 1105	North/South Line South	Feet from the 1150	East/West Line West	County: San Juan
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	------------------

Latitude 36.69333 Longitude 108.05589

**NATURE OF RELEASE**

Type of Release: unknown hydrocarbon	Volume of Release: unknown	Volume Recovered: none
Source of Release: unknown	Date and Hour of Occurrence: unknown	Date and Hour of Discovery: 9/11/2013
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell – NMOCD	
By Whom? Courtney Cochran – BP	Date and Hour: 2:00 pm – 9/11/2013	RCVD SEP 20 '13
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. OIL CONS. DIV. DIST. 3	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

While performing BGT sampling confirmation impacted soil was discovered. Further investigation will be needed to delineate the impacts.

Describe Area Affected and Cleanup Action Taken.\*

Upon further delineation a remedial plan will be developed. Excavation will most likely be the means of remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Courtney Cochran	Approved by Environmental Specialist 	
Title: Field Environmental Advisor	Approval Date: 10/23/2013	Expiration Date:
E-mail Address: Courtney.Cochran@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 9/18/2013 Phone: 505-326-9457		

\* Attach Additional Sheets If Necessary

nJK 1329652721