

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Burlington Resources Oil & Gas Company	Contact Crystal Tafoya	
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9837	
Facility Name: Marx Federal 1M	Facility Type: Gas Well	
Surface Owner BLM	Mineral Owner BLM (SF-078138)	API No. 30-045-33924

LOCATION OF RELEASE

Unit Letter N	Section 20	Township 30N	Range 11W	Feet from the 945	North/South Line South	Feet from the 1470	East/West Line West	County San Juan
-------------------------	----------------------	------------------------	---------------------	-----------------------------	----------------------------------	------------------------------	-------------------------------	---------------------------

Latitude **36.7931** Longitude **108.01733**

NATURE OF RELEASE

Type of Release Produced Water/Hydrocarbon	Volume of Release 60bbls/2bbls	Volume Recovered 59bbls/1bbl
Source of Release Production Pit	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 9/5/2013 at 11:00AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Shari Ketcham (BLM) & Jonathan Kelly (OCD)	
By Whom? Crystal Tafoya	Date and Hour 9/6/2013 at 8:03AM	REC'D SEP 12 '13
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. OIL CONS. DIV. DIST. 3	
If a Watercourse was Impacted, Describe Fully.* N/A		



Describe Cause of Problem and Remedial Action Taken.*

Discovered corrosion hole in production pit allowing 62bbls of produced water and hydrocarbon to be released into secondary containment. Immediately shut-in the well and dispatched a water truck. Recovered 59bbls of produced water and 1bbls of hydrocarbon.

Describe Area Affected and Cleanup Action Taken.*

The production pit is located within full secondary containment. The pit will be removed from the secondary containment and the soil will be inspected to determine a path forward for clean-up if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Crystal Tafoya		Approved by Environmental Specialist: 	
Title: Field Environmental Specialist		Approval Date: 10/23/2013	Expiration Date:
E-mail Address: crystal.tafoya@conocophillips.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 9/11/2013	Phone: (505) 326-9837		

* Attach Additional Sheets If Necessary

NJK1329654855