



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OCT 25 2013

Date of Test _____ Operator Elm Ridge Exploration CO LLC API #30-039-22696

Property Name Puppa Manche Well No. 005 Location: Unit B Section 35 Township 24N Range 01W

Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate _____ Casing 20 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>20</u>		
10 min	<u>0</u>		<u>20</u>		
15 min	<u>0</u>		<u>20</u>		
20 min	<u>0</u>		<u>20</u>		
25 min	<u>0</u>		<u>20</u>		
30 min	<u>0</u>		<u>20</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <input checked="" type="checkbox"/>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

Well Logged OFF Pumps Water only

By Frank Welch

Witness _____

pumper
(Position)

E-mail address _____