

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test: 05/22/13 Operator: RESOURCE DEVELOPMENT TECHNOLOGY, LLC API #30-039-05127									
Property Name: YARBOROUGH FED 'B' Well No. 1 Location: Unit D Section 10 Township 23N Range 6W									
Well Status(Shut-In or <u>Producing</u> ) Initial PSI: Tubing: <u>65</u> Intermediate: <u>NA</u> Casing: <u>75</u> Bradenhead: <u>0</u>									
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH									
<u>PRESSURE</u> <u>FLOW</u>								CHARACTERISTICS	
Testing Bradenhead				Intern	nediate	<b>     </b>		Bradenhead	Intermediate
Time	ВН	Int	Csg	Int	Csg	_###		Flowed	Flowed
5 Min	0	NA	75	NA	NA		Steady Flow		NA
10 Min	0	NA	75	NA	NA	_##	Surges		NA
15 Min	. 0	NA	75	NA	NA		Down to Nothing		NA
20 Min	0	NA	76	NA	NA		Nothing	x	NA
25 Min	0	NA	76	NA	NA		Gas		NA
30 Min	0	NA	76	NA	NA		Gas & Water		NA
							Water		NA
OIL CONS. DIV DIST. 3									
If bradenhead flowed water, check all of the descriptions that apply below:									
CI	.EAR	SALTY	SALTY SULFUR BLACK				OC1 2 1 2013		
5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE: NA									
REMARKS: pumpjack was in off cycle.									
	····	. <u> </u>							
By: Morga	Witne	ess							
Le	ase Operator						,		

E-mail address: morganholloway1943@comcast.net

(Position)