

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334.6478 FOX (505) 334.64

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(submit 2 copies to above address) \_\_

Date of Test	t 05/22/2013 Op	perator: Resour	ce Development Techno	ology, LLC API	#: 30-0 <u><b>39-22923</b></u>
	me: Theodore Zink I nit: D Section: 15 To				
Well Status	(Shut-In or <u><b>Producing</b></u>	g) Tubing_83	Intermediat N/A Casi	ng 72 Brader	nhead_0
OPEN BR	ADENHEAD AND IN	TERMEDIATE T	O ATMOSPHERE INDIV	IDUALLY FOR 15	MINUTES EACH
TIME	PRESSURES: INTERMEDIATE	CASING	_	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	NA	72	Steady Flow	0	NA
10 minutes	NA	72	Surges	00	NA
15 minutes	NA	72	Down to Nothing	0	NA
20 minutes	NA	72	Nothing	x	NA
25 minutes	NA	73	Gas	0	NA
30 minutes	NA	73	Gas & Water	00	NA
			Water	0	NA
If bradenhead	l flowed water, check all	of the description	s that apply below:	OILCO	NS. DIV DIST. 3
CLEAR FRESH SALTY			SULFUR BLACI	OCT 2 1 2013	
5 MINUTE SI	HUT-IN BRADENHE	AD0	INTERMEDIATE	<u>.</u>	
REMARKS: p	oump jack was in off cycle				
				,	
By Morgan I	<u> Holloway</u>		Witness		
Lease Opera (Posi	ator Pumper tion)		_		
E-mail address	morganhollowayt1943@	comcast.net			