



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test: 05/24/2013 Operator: RESOURCE DEVELOPMENT TECHNOLOGY, LLC API #30-039-23091

Property Name: SALAZAR 'G' FED COM 22 Well No. 3 Location: Unit E Section 22 Township 25N Range 6W

Well Status(Shut-In or **Producing**) Initial PSI: Tubing: 80 Intermediate: NA Casing: 90 Bradenhead: 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

FLOW CHARACTERISTICS

Testing Time	Bradenhead			Intermediate			Bradenhead		Intermediate
	BH	Int	Csg	Int	Csg		Flowed	Flowed	
5 Min	0	NA	90	NA	NA	Steady Flow	N	NA	
10 Min	0	NA	90	NA	NA	Surges	N	NA	
15 Min	0	NA	90	NA	NA	Down to Nothing	N	NA	
20 Min	0	NA	91	NA	NA	Nothing	Y	NA	
25 Min	0	NA	91	NA	NA	Gas	N	NA	
30 Min	0	NA	91	NA	NA	Gas & Water	N	NA	
						Water	N	NA	

OIL CONS. DIV DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

OCT 21 2013

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE: NA

REMARKS: Pump jack was in off cycle.

By: Morgan Holloway Witness _____

Lease Operator -- Pumper
(Position)

E-mail address: morganholloway1943@comcast.net