

Form 3160-5

UNITED STATES

FORM APPROVED

(August 2007)	DEPARTMENT OF THE BUREAU OF LAND MAI	TA CENTER			
BUREAU OF LAND MANAGEMENT Farmington Field Bureau of Land Wis SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an		i Wia nagemer Serial No. 6. If Indian, Allottee or Tribe N	STLESS Serial No. 11agemeii: SF-080712A 6. If Indian, Allottee or Tribe Name		
	e this form for proposals well. Use Form 3160-3 (A				
SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well			7. If Unit of CA/Agreement, Na	7. If Unit of CA/Agreement, Name and/or No. San Juan 30-6 Unit	
Oil Well X Gas Well Other			8. Well Name and No.		
2. Name of Operator Burlington Resources Oil & Gas Company LP .			9. API Well No.	9. API Well No. 30-039-27745	
3a. Address PO Box 4289, Farmington, NM 87499		3b. Phone No. (include area code (505) 326-9700	•	10. Field and Pool or Exploratory Area Basin FC	
4. Location of Well (Footage, Sec., T.,I Surface UL: F (SENW	R.,M., or Survey Description)), 1760' FNL & 1875' FWL,	Sec. 29, T30N, R6W	11. Country or Parish, State Rio Arriba ,	New Mexico	
12. CHECK	THE APPROPRIATE BOX(ES) TO INDICATE NATURE O	F NOTICE, REPORT OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off	
X Subsequent Report	Alter Casing Casing Repair	Fracture Treat New Construction	Reclamation Recomplete	Well Integrity X Other Legacy	
Subsequent Report	Change Plans	Plug and Abandon	Temporarily Abandon	Reclamation	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal		
Attach the bond under which the w following completion of the involv Testing has been completed. Final determined that the site is ready fo Burlington Resources Oil	onally or recomplete horizontally, give vork will be performed or provide the ed operations. If the operation results Abandonment Notices must be filed in final inspection.) and Gas Company LP componsite inspection. Please s	e subsurface locations and measure Bond No. on file with BLM/BIA. s in a multiple completion or recom only after all requirements, includi	ate of any proposed work and approxing and and true vertical depths of all pertined. Required subsequent reports must be furtherion in a new interval, a Form 3160-ing reclamation, have been completed a mation of the Location on 7/3 to verify Burlington Resourc	nt markers and zones. Filed within 30 days -4 must be filed once and the operator has 81/13, as requested by ses has met the BLM	
			OCT 2 FARMINGTON BY	FIELD OFFICE	
				RCVD OCT 29'13 OIL CONS. DIV. DIST. 3	
14. I hereby certify that the foregoing i	s true and correct. Name (Printed/Ty	ped)			
	Kenny Davis	Title	STAFF REGULATOR	RY TECHNICIAN	
			- 8/11	10/13	

entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would

Approved by

Title

Office

ConocoPhillips

Legacy

Reclamation Form:
Date: 8-12-20/3
Well Name: 5330-6 4795
Footages: 1760 FNL, 1875 FWL Unit Letter:
Section: <u>29</u> , T- <u>30</u> -N, R- <u>6</u> -W, County: <u>RA</u> State: <u>NM</u>
Reclamation Contractor: Ace
Reclamation Start Date: 7-31-13
Reclamation Complete Date: 7-31-/3
Road Completion Date: N/A
Seeding Date: 8-6-2013
**PIT MARKER STATUS (When Required): Picture of Marker set needed
MARKER PLACED :(DATE)
LATATUDE:
LONGITUDE:
Pit Manifold removed(DATE)
Construction Inspector: Norman Faver Date: 8-12-13
Inspector Signature: Norman Jav
Office Use Only: SubtaskDSMFolderPictures
Revised 6/14/2012

ConocoPhillips

ENGINEERING CALCULATION

53 30-6 4795

onsite BLM Mike Construct erros; on Er 41.08104 Repair errosion Reseal Pickup Trash