

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Conoco Burlington Resources, a Wholly Owned Subsidiary of ConocoPhillips Company	Contact Lisa Hunter
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9786
Facility Name: San Juan 30-6 #97	Facility Type: Gas Well

Surface Owner Federal	Mineral Owner Federal	API No. 3003907767
------------------------------	------------------------------	---------------------------

LOCATION OF RELEASE

Unit Letter G	Section 27	Township 30N	Range 7W	Feet from the 1485'	North/South Line North	Feet from the 1695'	East/West Line East	County Rio Arriba
-------------------------	----------------------	------------------------	--------------------	-------------------------------	----------------------------------	-------------------------------	-------------------------------	-----------------------------

Latitude 36.7867 Longitude -107.55437

NATURE OF RELEASE



Type of Release Produced Water	Volume of Release 9.3 BBLs	Volume Recovered 0 BBLs
Source of Release Oil/Production Tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 10/17/13 1:15 p.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? N/A	Date and Hour N/A	RCVD OCT 22 '13
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. OIL CONS. DIV.	
DIST. 3		

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Found tank leaking due to corrosion at weld seam. Well shut-in, hole plugged, and contents removed.

Describe Area Affected and Cleanup Action Taken.*
ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Lisa Hunter		Approved by Environmental Specialist: 	
Title: Field Environmental Specialist		Approval Date: 11/7/2013	Expiration Date:
E-mail Address: Lisa.Hunter@cop.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: October 21, 2013 Phone: (505) 326-9786			

* Attach Additional Sheets If Necessary

NSK 13311 32684