Office	State of	new me	XICO	Form C-103
District I	Energy, Minerals	and Natu	ral Resources	Jun 19, 2008
1625 N. French Dr., Hobbs, NM 88240				WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION			30-045-25676 5. Indicate Type of Lease	
District III 1220 South St. Francis Dr.			STATE FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505			6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505		,		FEE
	CES AND REPORTS OF	N WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Decker A	
1. Type of Well: Oil Well Gas Well Other			8. Well Number 2E	
2. Name of Operator			9. OGRID Number	
Burlington Resources Oil Gas Company LP 3. Address of Operator			14538 10. Pool name or Wildcat	
P.O. Box 4289, Farmington, NM 87499-4289			Basin Dakota	
				Dasiii Dakota
4. Well Location	C . C 1	T 48	1' 1 102	
Unit Letter B: 790 feet from the North line and 1830 feet from the East line				
Section 3	Township 31N		nge 12W	NMPM San Juan County
	11. Elevation (Show wh			1 Same of the second of
6168' GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
12. CHECK A	ppropriate box to in	uicale in	ature or notice,	Report of Other Data
NOTICE OF IN	TENTION TO:		SUE	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOR				RK ALTERING CASING
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DR				
PULL OR ALTER CASING	MULTIPLE COMPL		CASING/CEMEN	т ЈОВ □ КСУО ОСТ 24'13
DOWNHOLE COMMINGLE				OIL CONS. DIV. DIST. 3
OTHER:		П	N	· -
OTHER:			△ Location is	ready for OCD inspection after P&A
All pits have been remediated in Rat hole and cellar have been fil A steel marker at least 4" in diar	led and leveled. Cathodi	c protection	on holes have been	
UNIT LETTER, SECTIO	N, TOWNSHIP, AND F	RANGE.	ALL INFORMAT	UARTER/QUARTER LOCATION OR TION HAS BEEN WELDED OR
PERMANENTLY STAMI	<u>PED ON THE MARKE</u>	<u>RS SURF</u>	ACE.	
The location has been leveled as other production equipment.	nearly as possible to orig	ginal grou	nd contour and has	been cleared of all junk, trash, flow lines and
Anchors, dead men, tie downs as	nd risers have been cut o	ff at least t	wo feet below gro	und level.
☐ If this is a one-well lease or last	remaining well on lease,	the battery	and pit location(s) have been remediated in compliance with
		l closure p	lan. All flow lines	, production equipment and junk have been
removed from lease and well loo	cation.			
	1 1 1 1 1 1		. 1 1	1 (D
	als have been removed. A	Portable ba	ases have been rem	oved. (Poured onsite concrete bases do not
have to be removed.)				
have to be removed.) Pipelines and flow lines have be	en abandoned in accorda			oved. (Poured onsite concrete bases do not
have to be removed.)	en abandoned in accorda			
have to be removed.) Pipelines and flow lines have be	en abandoned in accorda ss.	nce with 1	9.15.35.10 NMAC	2. All fluids have been removed from non-
have to be removed.) Pipelines and flow lines have be retrieved flow lines and pipeline	en abandoned in accorda ss.	nce with 1	9.15.35.10 NMAC	2. All fluids have been removed from non-
have to be removed.) Pipelines and flow lines have be retrieved flow lines and pipeline	en abandoned in accorda ss.	nce with 1	9.15.35.10 NMAC	2. All fluids have been removed from non-
have to be removed.) Pipelines and flow lines have be retrieved flow lines and pipeline When all work has been completed, r	en abandoned in accordaes. The seturn this form to the app	nce with 1	9.15.35.10 NMAC	C. All fluids have been removed from non-hedule an inspection.
have to be removed.) Pipelines and flow lines have be retrieved flow lines and pipeline	en abandoned in accordaes. The seturn this form to the app	nce with 1	9.15.35.10 NMAC	2. All fluids have been removed from non-
have to be removed.) Pipelines and flow lines have be retrieved flow lines and pipeline When all work has been completed, respectively.	en abandoned in accordaes. The seturn this form to the app	nce with 1 propriate I	9.15.35.10 NMAC District office to scheme	2. All fluids have been removed from non-hedule an inspection. y Technician DATEDATEDATE
have to be removed.) Pipelines and flow lines have be retrieved flow lines and pipeline When all work has been completed, respectively.	en abandoned in accordance. The seturn this form to the applace of the seturn this form the seturn the seturn this form the seturn this form the seturn t	nce with 1 propriate I	9.15.35.10 NMAC District office to scheme Staff Regulator 1.busse@conocopl Puty Oll & Ga	All fluids have been removed from non-hedule an inspection. y Technician DATE
have to be removed.) Pipelines and flow lines have be retrieved flow lines and pipeline When all work has been completed, respectively. SIGNATURE Type or print name Dollie L. Buss For State Use Only	en abandoned in accordances. The treatment of the appropriate of the	nce with 1 propriate I TITLE	9.15.35.10 NMAC District office to scheme	All fluids have been removed from non-hedule an inspection. y Technician DATE
have to be removed.) Pipelines and flow lines have be retrieved flow lines and pipeline When all work has been completed, respectively. SIGNATURE Type or print name Dollie L. Buss	en abandoned in accordances. The treatment of the appropriate of the	nce with 1 propriate I	9.15.35.10 NMAC District office to scheme Staff Regulator 1.busse@conocopl Puty Oll & Ga	All fluids have been removed from non-hedule an inspection. y Technician DATE

/Durham, John, EMNRD

From:

Busse, Dollie L < Dollie.L.Busse@conocophillips.com>

Sent:

Monday, November 04, 2013 1:25 PM

To:

Durham, John, EMNRD

Subject:

FW: Decker A 2E (3004525676) - P&A/Cathodic Equipment

Hi John,

My information below was incorrect, the Cathodic equipment Teft on location is servicing the Decker A 3 (3004520743). Please let me know if you have any questions or need additional information.

Thanks!
Dollie

From: Busse, Dollie L

Sent: Monday, November 04, 2013 10:59 AM

To: John.Durham@state.nm.us

Subject: Decker A 2E (3004525676) - P&A/Cathodic Equipment

Hi John,

I've found the Decker A 2F that is scheduled to be P&A'd early in 2014 and the Decker A 1B that is producing. I'm waiting for confirmation that the Cathodic equipment left on location at the Decker A 2E was left to protect these wells.

They are all in Section 3, T31N, R12W. I'll let you know as soon as I hear back.

Thanks for the heads up!

Dollie

Dollie L. Busse | Staff Regulatory Technicían | ConocoPhillips | San Juan Business Unit | P.O. Box 4289 | Farmington, NM 87499 | Office: 505-324-6104 | E-mail: dollie.l.busse@cop.com

Safety People Integrity Responsibility Innovation Teamwork