



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

AUG 21 2013

Date of Test 8-12-13 Operator [Signature] API #30-0 39-23501
Property Name 5530-6 3WD Well No. 1124 Location: Unit Section 24 Township 30 Range 6
Well Status(Shut-In or Producing) Initial PSI: Tubing 297 Intermediate 3.5 Casing -7 Bradenhead 0.2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM		
	BH	Int	Csg	Int	Csg	
5 min	0	5.3	-7	0	-7	
10 min	0	5.7	-7	0	-7	
15 min	0	5.9	-7	0	-7	
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓ Puff
Nothing	✓
Gas	✓
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

BH. Puff, Int. =

By

(Position)

Witness

E-mail address