



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

**ENTERED**  
17-23-13  
ja  
OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emrdr.state.nm.us/ocd/District III/3district.htm](http://emrdr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

**BRADENHEAD TEST REPORT**

AUG 20 2013

(submit 1 copy to above address)

Date of Test 4-5-13 Operator Delson API #30-0 39 29933

Property Name NEBU Well No. 493A Location: Unit H Section 25 Township 31N Range 7W

Well Status(Shut-In or Producing) Initial PSI: Tubing 1 Intermediate N/A Casing 5 Bradenhead 3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0	N/A	5		
10 min	0		5		
15 min	0		5		
20 min	0		5		
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		✓
Nothing		
Gas		✓
Gas & Water		
Water		

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By DAN MCELLEGAN  
LEASE OPERATOR  
(Position)

Witness RYAN MOSLEY

E-mail address \_\_\_\_\_

input