

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178 FAX: (505) 334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

AUG 2 0 2013

Date of Test 4-8-13 Operat	or Devon API#30-0 3924399
Property Name NeBU Well No. 483 Location: Unit & Section 36 Township 3/4 Range 7 w	
Well Status(Shut-In or Producing) Initial PSI: Tubing / Intermediate / Casing /O Bradenhead 3	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min 6 w/x 10	Steady Flow
10 min 0 10	Surges
15 min 0 10	Down to Nothing $\boldsymbol{\nu}$
20 min 0 10	Nothing
25 min	Gas
30 min_	Gas & Water
	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR_ FRESH SALTY SULFUR BLACK	
SMINUTE SHUT-IN PRESSURE BRADENHEAD () INTERMEDIATE N/A REMARKS: BRATDEN BURDED APRX / CUSP CLAR LATER	
WHEN FERST OPENED,	
By DAN MELLEGAN Witness Intly Pachee (Position) Witness Intly Pachee	
E-mail address	