

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Conoco Burlington Resources, a Wholly Owned Subsidiary of ConocoPhillips Company	Contact Lisa Hunter
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9786
Facility Name: Albino Canyon Unit 100S	Facility Type: Gas Well

Surface Owner State	Mineral Owner State	API No. 3004531265
----------------------------	----------------------------	---------------------------

LOCATION OF RELEASE

Unit Letter J	Section 36	Township 32N	Range 8W	Feet from the 2050'	North/South Line South	Feet from the 1735	East/West Line East	County San Juan
-------------------------	----------------------	------------------------	--------------------	-------------------------------	----------------------------------	------------------------------	-------------------------------	---------------------------

Latitude **36.93809** Longitude **-107.62322**

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 10.7 BBL	Volume Recovered 10 BBL
Source of Release Water Tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 10/28/13 @ 11:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour RCVD NOV 15 '13	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. OIL CONS. DIV. DIST. 3	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

While performing maintenance, MSO noticed some standing water in the berm. MSO noticed High Level Detection Radar had not been removed from tank taken out of service to an in-service tank, causing tank overflow. Pumping unit shut off and recovered standing fluids.

Describe Area Affected and Cleanup Action Taken.*

ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Lisa Hunter	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 11/26/2013	Expiration Date:
E-mail Address: Lisa.Hunter@cop.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: November 12, 2013 Phone: (505) 326-9786		

* Attach Additional Sheets If Necessary

NDK1333054347