

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

**OIL CONS. DIV DIST. 3**

**DEC 06 2013**

Date of Test 06/18/2013 Operator ENCANA API #30-0 45-35341

Property Name BISTI HO9-2510-#01H Well No. 01H Location: Unit H Section 9 Township 25N Range 10

Pressure (Shut-In or Producing) PRODUCING Tubing 41 Intermediate 0 Casing 38 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:				BRADENHEAD	INTERMEDIATE
	BRADENHEAD	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes				Steady Flow		
10 minutes				Surges		
15 minutes				Down to Nothing		
20 minutes				Nothing		
25 minutes				Gas		
30 minutes				Gas & Water		
				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD \_\_\_\_\_ INTERMEDIATE \_\_\_\_\_

REMARKS:

BRADENHEAD IS ZERO PSI

By Jason Chestnut Witness \_\_\_\_\_

Lease Operator

(Position)

E-mail address Jason@walsheng.net