Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 31,2010

	Expires: July 3
ana Carial Ma	

					5. Lease Serial No.	F-078922	
SUNDRY NOTICES AND REPORTS ON WELLS					6. If Indian, Allottee or Tribe		
Do not use this form for proposals to drill or to re-enter an					o. It ilidiali, Allottee of Tribe	Name	
abandoned							
SUBMIT IN TRIPLICATE - Other instructions on page 2.					7./Îf Unit of CA/Agreement, Name and/or No.		
1 70 CUT II				Canyon Largo Unit			
Oil Well	NOV 19 2013		8. Well Name and No.				
2 Name of Oreston		Nepre	trocken to a		9. API Well No.	argo Unit NP	158
	ton Resources Oil & Gas	Compan		r	30-C	39-20282	
3a. Address PO Box 4289, Farmington, NM 87499		3b. Phone No. (include area code) (505) 326-9700		10. Field and Pool or Exploratory Area Ballard PC			
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)		L	(000) 020 0100		11. Country or Parish, State		
	WSE), 1650' FSL & 1650'	FEL, Se	:. 1, T24N, I	R7W	Rio Arriba	, New Mex	ico
12. CHECK T	HE APPROPRIATE BOX(ES)	TO INDIC	ATE NATUR	E OF NO	TICE, REPORT OR OTH	ER DATA	
TYPE OF SUBMISSION			TYPI	OF AC	TION		
Notice of Intent	Acidize	Deepe	n	P	roduction (Start/Resume)	Water Shut-0	Off
· —	Alter Casing	Fractu	re Treat	R	teclamation	Well Integrit	у
X Subsequent Report	Casing Repair	New C	Construction	☐ R	Recomplete	Other	
	Change Plans	=	nd Abandon		emporarily Abandon		
Final Abandonment Notice 13. Describe Proposed or Completed O	Convert to Injection	Plug E			Vater Disposal	. <u> </u>	
Testing has been completed. Fina determined that the site is ready for	red operations. If the operation result l Abandonment Notices must be filed or final inspection.)	l only after al	I requirements, i	including re	clamation, have been complete	d and the operator h	as
10/17/13 Received verl	oal approval from Mark Dek	cer (BLN	l-onsite) and	d Charlie	Perrin (NMOCD) to co	ombine plugs 1	& 2.
This well was P&A'd	on 10/21/13 per the above	notificat	ion and att	ached re	eport.	RCVD DEC 2.1	19
					OIL CONS, DIV.		
					•	DIST. 3	¥.
						VI31.3	
14. I hereby certify that the foregoing i	s true and correct. Name (Printed/Ty	pped)					
Denise Journey Title			Title Regul	le Regulatory Technician			
Signature Dining Triving			11/18/2013 Date				
	THIS SPACE FO	R FEDE	RAL OR ST	ATE OFF	ICE USE		-
Approved by							
				Title		Date	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify			Office				
Title 18 U.S.C. Section 1001 and Title false, fictitious or fraudulent statements				y and willful	lly to make to any department of	or agency of the Unit	ed States any
(Instruction on page 2)							

NMOCDA

NOV 2 5 2013 FARMAGTON FIELD OFFICE

ASSEPTEMENT RECORD



A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Burlington Resources
Canyon Largo Unit NP 158

October 21, 2013 Page 1 of 1

1650' FSL and 1650' FEL, Section 1, T-24-N, R-7-W Rio Arriba County, NM Lease Number: SF-078922 API #30-039-20282

Plug and Abandonment Report
Notified NMOCD and BLM on 10/15/13

Plug and Abandonment Summary:

- Plug #1 (combined #2) with 20 sxs (21.18 cf) Class B cement inside casing from 2182' to 1510' to cover the Pictured Cliffs, Fruitland, Kirtland and Ojo Alamo tops.
- Plug #3 with 64 sxs (84.96 cf) Class B cement inside casing from 185' to surface to cover the Nacimiento and surface casing shoe.
- Plug #4 with 25 sxs Class B cement top off casing and install P&A marker.

Plugging Work Details:

- 10/15/13 Rode rig equipment to location. Spot in and RU. SI well. SDFD.
- 10/16/13 Check well pressures: casing 220 PSI, tubing 60 PSI and bradenhead 0 PSI. RU and blow down well. X-over to 1-1/4" pipe rams. Pump 20 bbls to kill well. ND WH. NU 2-7/8" companion flange and BOP. Function test pipe rams, OK. POH and tally 34 stands, LD 1 jnt, no pin collar as reported, 69 jnts 1-1/4 IJ tubing 2238'. RIH with 2-7/8" GR to 2200'. RIH and set 2-7/8" PW CIBP set at 2182'. TIH with tubing 34 stands, tag with 1 jnt, LD 1 jnt. SI well. SDFD.
- 10/17/13 Open up well; no pressures. Bump test H2S equipment. Circulate well clean with 17 bbls. Pressure test casing to 800 PSI, OK. RU Basin Wireline. Ran CBL from 2182' to surface, estimated TOC at 1390'. Spot plug #1 (combined #2) with estimated TOC at 1510'. Note: S. Mason, BLM and B. Powell, NMOCD approved procedure change. Perforate 4 bi-wire holes at 185'. Spot plug #2 with estimated TOC at surface. Attempt to squeeze pump 1/8-1/4 bbl with no pressure. SI well. SDFD.
- 10/21/13 Open up well; no pressures. Bump test H2S equipment. ND BOP and dig out wellhead. RU Hot Work Permit. RU High Desert and cut off wellhead. Found cement down 50' in casing and 3' in bradenhead. Spot plug #4 to top off casings and install P&A marker. RD and MOL.

Mark Decker, BLM representative, was on location. Jason Vasquez, COPC representative, was on location.