



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distrct.htm](http://emnr.state.nm.us/ocd/District%20III/3distrct.htm)

RCVD JAN 17 '14
OIL CONS. DIV.

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DIST. 3

Date of Test 1-17-14 Operator Chuzadil Co API #30-0 45-30090
Property Name DE Hogback Well No. 52 Location: Unit I Section 10 Township 30 Range 16
Well Status (Shut-In or Producing) Initial PSI: Tubing 7 Intermediate V/A Casing 4 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>4</u>		
10 min	<u>0</u>		<u>4</u>		
15 min	<u>0</u>		<u>4</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>/</u>
Nothing	
Gas	<u>/</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE V/A

REMARKS:

Puff when opened.

By Christopher L. Bance

Witness Monica Tackling

(Position)

E-mail address _____