



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 2-11-14 Operator Domunion API #30-0 31-20119
Property Name South Hays Lake Well No. 35 Location: Unit A Section 12 Township 19 Range 9
Well Status (Shut-In or Producing) Initial PSI: Tubing 125 Intermediate 1/1 Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>0</u>		
10 min	<u>0</u>		<u>0</u>		
15 min	<u>0</u>		<u>0</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	<u>DIST. 3</u>
Surges	
Down to Nothing	<u>OIL CONS. DIV.</u>
Nothing	<u>/</u>
Gas	<u>PCUD FEB 11 '14</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 1/1

REMARKS:

Casing on Vacuum - nothing on bh when
opened.
No well sign. Cannot take picture. Cannot pump
By Raymond Brown Witness Monica Kuehling

(Position)

E-mail address _____