

State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

David Martin
Cabinet Secretary

Brett F. Woods, Ph.D.
Deputy Cabinet Secretary

Jami Bailey, Division Director
Oil Conservation Division



February 18, 2014

Cross Timbers Energy LLC
Justin Z Neely
400 West 7th Street
Ft. Worth, TX 75070

RE: Information request

Dear Mr. Neely:

After review of previously submitted bradenhead tests, it was found that the wells listed below had water flow, high pressure on bradenhead and/or intermediate, or no bradenhead valve. Please submit gas and water analysis on all casing strings and a current wellbore schematic for each well within 30 days from the date of this letter.

Well Name & No.	UL	SEC	TWN	RGE	API#
Breech E #87	J	4	26N	6W	30-039-06687
Miles Federal #1A	F	5	26N	7W	30-039-22916
MKL #6	D	6	26N	7W	30-039-06751
MKL #19	B	8	26N	7W	30-039-06621

If you have any questions, please call me at 505-334-6178, ext. 123.

Sincerely yours,

Monica Kuehling
Deputy Oil and Gas Inspector
District III - Aztec

CC: Well File