



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emmr.state.nm.us/ocd/District III/3district.htm](http://emmr.state.nm.us/ocd/District%20III/3district.htm)

RCVD MAR 12 '14
OIL CONS. DIV.
DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3-12-14 Operator Monument Prod. API #30-0 31-20120
Property Name South Hoss Park W. Well No. 29 Location: Unit B Section 12 Township 17 Range 9
Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 175 Intermediate N/A Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>0</u>		
10 min	<u>0</u>		<u>0</u>		
15 min	<u>0</u>		<u>0</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing

Nothing ✓

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Nothing when opened.

Can bury with good valve

By Ray Lopez

Witness Mona Luehling

(Position)

E-mail address _____