



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District III/3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3-11-14 Operator Burlington API #30-0 39-24518
Property Name San Juan 30-6 let SWD Well No. 2 Location: Unit 23 Section 23 Township 30 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 604 Intermediate V/A Casing 7 Bradenhead 15

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
5 min	<u>29</u>		<u>-7</u>		
10 min	<u>21</u>		<u>-7</u>		
15 min	<u>14</u>		<u>-7</u>		
20 min	<u>9</u>		<u>-7</u>		
25 min	<u>5</u>		<u>-7</u>		
30 min	<u>3</u>		<u>-7</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>1/2"</u>	
Surges	<u>RCVD MAR 11 '14</u>
Down to Nothing	
Nothing	<u>OIL CONS. DIV.</u>
Gas	<u>DIST. 3</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 3 INTERMEDIATE V/A

REMARKS: BH blown through 1/2" valve - lower blowdown
Nelson schedule to test once a year with Gas
Analysis on Casing & BH annually

By David Aguirre
SWD M30
(Position)

Witness Monica Kuehling

E-mail address david.h.aguirre@cop.com