



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://omnrd.state.nm.us/ocd/District III/3district.htm](http://omnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3-17-14 Operator Wurton Energy API #30-0 39-29856
Property Name VEBU Well No. 238 Location: Unit Section 25 Township 31 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 83 Intermediate V/A Casing 90 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0		93		
10 min	0		94		
15 min	0		95		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	DIST. 2
Nothing	
Gas	OIL CONS. DIV.
Gas & Water	RCVD MAR 17 '14
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE V/A

REMARKS:

Nothing when opened.

By [Signature]

Witness [Signature]

(Position)

E-mail address