



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/DistrictIII/3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3-11-14 Operator David Aguirre API #30-0 39-24518
Property Name SJ 30.4#520 Well No. #2 Location: Unit Section 23 Township 30 Range 7
Well Status(Shut-In or Producing) Initial PSI: Tubing 624 Intermediate - Casing -7 Bradenhead 45

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM		
	BH	Int	Csg	Int	Csg	
TIME						
5 min	29		-7			
10 min	21		-7			
15 min	14		-7			
20 min	9		-7			
25 min	5		-7			
30 min	3		-7			

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>@ 3 psi @ 30 min.</u>	
Surges	
Down to Nothing	RCUD MAR 20 '14
Nothing	OIL CONS. DIV.
Gas	DIST. 3
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 3 INTERMEDIATE -

REMARKS: BH blows & trough 1/2" valve. Did not blow down. Need to re-schedule
once a year w/ gas analysis on casing & BH. annulus

By David Aguirre
Shed MSO
(Position)

Witness _____

E-mail address _____