

NEW MEXICO ENERGY, MUNERALS & NATURAL RIESOURCES IDEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

RCVD MAR 27'14 OIL CONS. DIU.

	(submit 1 copy to above address)	D151.3
Date of Test 3-21-14	Operator Kobut L. Day API # Well No Location: Unit Section_	130-0 45-09630
Well Status(Shut-In or Producing) Initial PSI: Tubing / Intermediate / Casing / Bradenhead 5		
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH		
PRESSURE Testing Bradenhead INTE BH Int Csg Int		ARACTERISTICS INTERMEDIATE
TIME 5 min 0 10	Steady Flow	
10 min 0 10	Surges_	
15 min 0 (70	Down to Nothing	
20 min	Nothing	
25 min_	Gas	
30 min_	Gas & Water	
Water		
If bradenhead flowed water, check all of the descriptions that apply below:		
CLEARFRESHS	SALTYBLACK	
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE THE		
REMARKS: bug blow to clead at 20 Deconds.		
	11	
By Branky Aran Witness / Would willing		
Position)		
E-mail address	<u> </u>	