



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III3district.htm](http://emnrd.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

RCVD APR 8 '14

OIL CONS. DIV.

DIST. 3

45-20755

20775

Date of Test 8-APR-2014 Operator CHAPARRAL API #30-0 20775

Property Name SHELLY Well No. 2 Location: Unit 6 Section 34 Township 27 Range 11

Well Status(Shut-In or Producing) Initial PSI: Tubing 5 Intermediate N/A Casing 5 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min			5		
10 min			5		
15 min			5		
20 min					
25 min					
30 min					

		FLOW CHARACTERISTICS	
		BRADENHEAD	INTERMEDIATE
Steady Flow			
Surges			
Down to Nothing			
Nothing	X		
Gas			
Gas & Water			
Water			

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS: OPENED THE BRADENHEAD AND NOTHING CAME OUT.

By Eit 3

Witness John DeWanna

(Position)

E-mail address _____