$\hat{\mathbf{O}}$

,

6

State of New Mexico Energy Minerals and Natural Resources Department Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

For temporary pits, closed-loop systems, and below-grade tanks, submit to the appropriate NMOCD District Office. For permanent pits and exceptions submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District Office.

| Pit, Closed-Loop System, Below-Grade Tank, or | |
|---|--|
| Proposed Alternative Method Permit or Closure Plan Applica | ation |
| Type of action: Permit of a pit, closed-loop system, below-grade tank, or proposed altern Closure of a pit, closed-loop system, below-grade tank, or proposed altern Modification to an existing permit Closure plan only submitted for an existing permitted or non-permitted p below-grade tank, or proposed alternative method | rnative method |
| Instructions: Please submit one application (Form C-144) per individual pit, closed-loop system, below-grade to | ank or alternative request |
| Please be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority. | ce water, ground water or the ty's rules, regulations or ordinances. |
| Operator: <u>WPX Energy Production, LLC</u> OGRID #: | |
| Address: PO Box 640 / 721 S Main Aztec, NM 87410 | |
| Facility or well name: <u>Chaco 2307-12E #168H (FKA Lybrook 23-7-12 #101H)</u> | |
| API Number: 30-039-31173 OCD Permit Number: 10943 | |
| U/L or Qtr/Qtr <u>E</u> Section <u>12</u> Township <u>23N</u> Range <u>7W</u> County: | |
| Center of Proposed Design: Latitude <u>36.24233</u> Longitude <u>-107.53485</u> | NAD: 🔲 1927 🔀 1983 |
| Surface Owner: 🛛 Federal 🗌 State 🗌 Private 🗌 Tribal Trust or Indian Allotment | |
| 2. ☑ Pit: Subsection F or G of 19.15.17.11 NMAC Temporary: ☑ Drilling □ Workover □ Permanent □ Emergency □ Cavitation □ P&A ☑ Lined □ Unlined Liner type: Thickness 20 mil ☑ LLDPE □ HDPE □ PVC □ Other ☑ String-Reinforced | 7 <u>0'</u> x D <u>15'</u> |
| Lined Unlined Liner type: Thicknessmil LLDPE HDPE PVC Other | |
| Liner Seams: 🗌 Welded 🗍 Factory 🔲 Other | |
| 4. Below-grade tank: Subsection I of 19.15.17.11 NMAC | RCUD MAR 20 '14 |
| Volume:bbl Type of fluid: | nil cens. DIV. |
| Tank Construction material: | |
| Secondary containment with leak detection 🗌 Visible sidewalls, liner, 6-inch lift and automatic overflow shut-off | JIST. 3 |
| □ Visible sidewalls and liner □ Visible sidewalls only □ Other | |
| Liner type: Thicknessmil | |
| <u>Alternative Method</u>: Submittal of an exception request is required. Exceptions must be submitted to the Santa Fe Environmental Bureau office | for consideration of approval. |

20

Fencing: Subsection D of 19.15.17.11 NMAC (Applies to permanent pits, temporary pits, and below-grade tanks)

Chain link, six feet in height, two strands of barbed wire at top (Required if located within 1000 feet of a permanent residence, school, hospital, institution or church)

Four foot height, four strands of barbed wire evenly spaced between one and four feet

Alternate. Please specify <u>As per BLM specifications</u>

Netting: Subsection E of 19.15.17.11 NMAC (Applies to permanent pits and permanent open top tanks)

Screen Netting Other_

7

9.

Monthly inspections (If netting or screening is not physically feasible)

Signs: Subsection C of 19.15.17.11 NMAC

12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers

Signed in compliance with 19.15.3.103 NMAC

Administrative Approvals and Exceptions:

Justifications and/or demonstrations of equivalency are required. Please refer to 19.15.17 NMAC for guidance.

Please check a box if one or more of the following is requested, if not leave blank:

Administrative approval(s): Requests must be submitted to the appropriate division district or the Santa Fe Environmental Bureau office for consideration of approval.

Exception(s): Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.

10. Siting Criteria (regarding permitting): 19.15.17.10 NMAC

| Siting Criteria (regarding permitting): 19.15.17.10 NMAC Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of acception material are provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appro office or may be considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of a Applicant must attach justification for request. Please refer to 19.15.17.10 NMAC for guidance. Siting criteria does not apply to dry above-grade tanks associated with a closed-loop system. | opriate district opproval. |
|--|-------------------------------|
| Ground water is less than 50 feet below the bottom of the temporary pit, permanent pit, or below-grade tank. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells | 🗋 Yes 🛛 No |
| Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). Topographic map; Visual inspection (certification) of the proposed site | 🔲 Yes 🖾 No |
| Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. (Applies to temporary, emergency, or cavitation pits and below-grade tanks) Visual inspection (certification) of the proposed site; Aerial photo; Satellite image | ☐ Yes ⊠ No ☐ NA |
| Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. (Applies to permanent pits) Visual inspection (certification) of the proposed site; Aerial photo; Satellite image | Yes No |
| Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application. NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site | 🗋 Yes 🛛 No |
| Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. Written confirmation or verification from the municipality; Written approval obtained from the municipality | 🔲 Yes 🖾 No |
| Within 500 feet of a wetland. US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site | 🗌 Yes 🛛 No |
| Within the area overlying a subsurface mine. Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division | 🗌 Yes 🛛 No |
| Within an unstable area. Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map | 🗌 Yes 🛛 No |
| Within a 100-year floodplain. | 🗌 Yes 🛛 No |

FEMA map

| ۲ ÷ | |
|--|--|
| 11. <u>Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Applicat</u> <i>Instructions: Each of the following items must be attached to the application</i> | |
| attached. A Hydrogeologic Report (Bclow-grade Tanks) - based upon the requirement A Hydrogeologic Data (Temporary and Emergency Pits) - based upon the result of the string Criteria Compliance Demonstrations - based upon the appropriate A Design Plan - based upon the appropriate requirements of 19.15.17.11 NI A Operating and Maintenance Plan - based upon the appropriate requirement A Closure Plan (Please complete Boxes 14 through 18, if applicable) - base | equirements of Paragraph (2) of Subsection B of 19.15.17.9 NMAC requirements of 19.15.17.10 NMAC MAC nts of 19.15.17.12 NMAC |
| and 19.15.17.13 NMAC | |
| Previously Approved Design (attach copy of design) API Number: | |
| and 19.15.17.13 NMAC | Please indicate, by a check mark in the box, that the documents are n the requirements of Paragraph (3) of Subsection B of 19.15.17.9 ased upon the appropriate requirements of 19.15.17.10 NMAC MAC ints of 19.15.17.12 NMAC ed upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC |
| | |
| Previously Approved Operating and Maintenance Plan API Number: | |
| above ground steel tanks or haul-off bins and propose to implement waste remo | oval for closure) |
| Permanent Pits Permit Application Checklist: Subsection B of 19.15.17.91 Instructions: Each of the following items must be attached to the application attached. Hydrogeologic Report - based upon the requirements of Paragraph (1) of Siting Criteria Compliance Demonstrations - based upon the appropriate Climatological Factors Assessment Certified Engineering Design Plans - based upon the appropriate requirements of 19. Liner Specifications and Structural Integrity Design - based upon the appropriate requirements of 19. Liner Specifications and Compatibility Assessment - based upon the appropriate requirements Quality Control/Quality Assurance Construction and Installation Plan Operating and Maintenance Plan - based upon the appropriate requirement Freeboard and Overtopping Prevention Plan - based upon the appropriate Nuisance or Hazardous Odors, including H₂S, Prevention Plan Emergency Response Plan Oil Field Waste Stream Characterization Monitoring and Inspection Plan Erosion Control Plan Closure Plan - based upon the appropriate requirements of Subsection C | Please indicate, by a check mark in the box, that the documents are Subsection B of 19.15.17.9 NMAC requirements of 19.15.17.10 NMAC ments of 19.15.17.11 NMAC tiate requirements of 19.15.17.11 NMAC 15.17.11 NMAC ropriate requirements of 19.15.17.11 NMAC nts of 19.15.17.12 NMAC e requirements of 19.15.17.11 NMAC |
| Proposed Closure: 19.15.17.13 NMAC Instructions: Please complete the applicable boxes, Boxes 14 through 18, in a Type: Drilling Workover Alternative Emergency Cavitation P&A Proposed Closure Method: Waste Excavation and Removal Waste Removal On-site Closure Method (Only for temporary pice) In-place Burial On-site Trench Alternative Closure Method (Exceptions must be) | Permanent Pit Below-grade Tank Closed-loop System its and closed-loop systems) |
| ^{15.} Waste Excavation and Removal Closure Plan Checklist: (19.15.17.13 NMA closure plan. Please indicate, by a check mark in the box, that the documents | AC) Instructions: Each of the following items must be attached to the s are attached. 9.15.17.13 NMAC requirements of Subsection F of 19.15.17.13 NMAC nd drill cuttings) ate requirements of Subsection H of 19.15.17.13 NMAC ion 1 of 19.15.17.13 NMAC |

| ^{16.} Waste Removal Closure For Closed-loop Systems That Utilize Above Ground Steel Tanks or Haul-off Bins Only: (19.15.17. | 13.D NMAC) |
|--|---------------------------|
| Instructions: Please identify the facility or facilities for the disposal of liquids, drilling fluids and drill cuttings. Use attachment facilities are required. | |
| Disposal Facility Name: Disposal Facility Permit Number: | |
| Disposal Facility Name: Disposal Facility Permit Number: | |
| Will any of the proposed closed-loop system operations and associated activities occur on or in areas that <i>will not</i> be used for future Yes (If yes, please provide the information below) No | |
| Required for impacted areas which will not be used for future service and operations: Soil Backfill and Cover Design Specifications based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19.15.17.13 NMAC Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC | МАС |
| ^{17.} <u>Siting Criteria (regarding on-site closure methods only)</u> : 19.15.17.10 NMAC Instructions: Each siting criteria requires a demonstration of compliance in the closure plan. Recommendations of acceptable of provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appropriate considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of approval. J demonstrations of equivalency are required. Please refer to 19.15.17.10 NMAC for guidance. | district office or may be |
| Ground water is less than 50 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells | ☐ Yes ⊠ No ☐ NA |
| Ground water is between 50 and 100 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells | ☐ Yes ⊠ No ☐ NA |
| Ground water is more than 100 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells | Yes No |
| Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or play lake (measured from the ordinary high-water mark). Topographic map; Visual inspection (certification) of the proposed site | a 🔲 Yes 🖾 No |
| Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. Visual inspection (certification) of the proposed site; Aerial photo; Satellite image | 🗌 Yes 🛛 No |
| Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application - NM Office of the State Engineer - iWATERS database; Visual inspection (certification) of the proposed site | n. 🗌 Yes 🖾 No |
| Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. Written confirmation or verification from the municipality; Written approval obtained from the municipality | 🗋 Yes 🖾 No |
| Within 500 feet of a wetland. US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site | 🗌 Yes 🛛 No |
| Within the area overlying a subsurface mine. Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division | 🗌 Yes 🛛 No |
| Within an unstable area. Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map | 🗋 Yes 🛛 No |
| Within a 100-year floodplain. - FEMA map | 🗌 Yes 🛛 No |
| 18. On-Site Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure by a check mark in the box, that the documents are attached. Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Proof of Surface Owner Notice - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC Construction/Design Plan of Burial Trench (if applicable) based upon the appropriate requirements of 19.15.17.13 NMAC Construction/Design Plan of Temporary Pit (for in-place burial of a drying pad) - based upon the appropriate requirements of 19.15.17.13 NMAC Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC Waste Material Sampling Plan - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC | 19.15.17.11 NMAC |

Waste Material Sampling Fian - based upon the appropriate requirements of Subsection For D.15.17.15 (MARC)
 Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings or in case on-site closure standards cannot be achieved)
 Soil Cover Design - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC
 Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19.15.17.13 NMAC

,

.

Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC

| 19. Operator Application Certification: | |
|---|--|
| I hereby certify that the information submitted with this application is true, a | |
| Name (Print): <u>Mark Heil</u> | Title: <u>Regulatory Specialist</u> |
| Signature: | Date: <u>3/20/2014</u> |
| e-mail address:mark.heil@wpxenergy.com | Telephone: <u>505-333-1806</u> |
| 20. <u>OCD Approva</u> l: Permit Application (including cldsure plan) Closu OCD Representative Signature: | Ire Plan (only) OCD Conditions (see attachment) Approval Date: 4/11/2014 OCD Permit Number: |
| ^{21.} <u>Closure Report (required within 60 days of closure completion)</u> : Subsect Instructions: Operators are required to obtain an approved closure plan put The closure report is required to be submitted to the division within 60 days section of the form until an approved closure plan has been obtained and the | rior to implementing any closure activities and submitting the closure report. s of the completion of the closure activities. Please do not complete this |
| 22. | |
| Closure Method: | ternative Closure Method 🔲 Waste Removal (Closed-loop systems only) |
| ^{23.} Closure Report Regarding Waste Removal Closure For Closed-loop Syst Instructions: Please indentify the facility or facilities for where the liquids, two facilities were utilized. | tems That Utilize Above Ground Steel Tanks or Haul-off Bins Only: , drilling fluids and drill cuttings were disposed. Use attachment if more than |
| Disposal Facility Name: | Disposal Facility Permit Number: |
| Disposal Facility Name: | |
| Were the closed-loop system operations and associated activities performed of Yes (If yes, please demonstrate compliance to the items below) | |
| Required for impacted areas which will not be used for future service and op Site Reclamation (Photo Documentation) Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique | erations: |
| 24. | |
| Closure Report Attachment Checklist: Instructions: Each of the following mark in the box, that the documents are attached. Proof of Closure Notice (surface owner and division) Proof of Deed Notice (required for on-site closure) Plot Plan (for on-site closures and temporary pits) Confirmation Sampling Analytical Results (if applicable) Waste Material Sampling Analytical Results (required for on-site closure) Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Site Reclamation (Photo Documentation) On-site Closure Location: Latitude | items must be attached to the closure report. Please indicate, by a check ure) Longitude -107.53485 NAD: \Box 1927 \boxtimes 1983 |
| | |
| 25. Operator Closure Certification: I hereby certify that the information and attachments submitted with this clos belief. I also certify that the closure complies with all applicable closure required. | ure report is true, accurate and complete to the best of my knowledge and irements and conditions specified in the approved closure plan. |
| Name (Print): <u>Mark Heil</u> | Title: <u>Regulatory Specialist</u> |
| Signature: Mccl | Date: <u>3/20/2014</u> |
| e-mail address:mark.heil@wpxenergy.com | Telephone: <u>505-333-1806</u> |

t 1

WPX Energy Production, LLC San Juan Basin: New Mexico Assets Temporary Pit In-place Closure Report Drilling/Completion and Workover (Groundwater >100 feet bgs)

| Well: | Chaco 2307-12E #168H |
|-----------|-----------------------|
| API No: | <u>30-039-31173</u> |
| Location: | E-S02-T22N-R07W, NMPM |

In accordance with Rule 19.15.17.13 NMAC, the following plan describes the general in-place closure requirements of temporary pits on WPX Energy Production, LLC (WPX) locations in the San Juan Basin of New Mexico. This is WPX's standard procedure for all temporary pits to be utilized for the drilling, completion and/or workovers of oil and gas wells operated by WPX. For those temporary pits which do not conform to this standard closure plan, a separate well/pit specific closure plan will be developed and utilized.

All closure activities will include proper documentation and will be submitted to OCD within 60 days of the pit closure on a Closure Report using Division Form C-144. The Report will include the following:

- Details on Capping and Covering, where applicable
- Plot Plan (Pit Diagram)
- Inspection reports
- Sampling Results
- Division Form C-105: WELL COMPLETION OR RECOMPLETION REPORT AND LOG
- Copy of Deed Notice filed with the County Clerk (format to meet County requirements)
 <u>A deed notice is not required on state, federal or tribal land according to NMOCD FAQ dated October 30, 2008 and posted on the NMOCD website.</u>

General Plan Requirements:

All free standing liquids will be removed from the pit at the start of the closure process. Liquids will be removed in a
manner that the appropriate District Office approves including; recycled, reused, reclaimed, evaporated, and/or disposed of
in a Division-approved facility. Once all free liquids are removed, the sludge will be stabilized by one of the following
methods depending on equipment availability: blending with clean stockpiled soils or dewatering using a Bowl Decanter
Centrifuge then blending with clean stockpiles soils.

Free liquids were not present at the reserve pit following the completion rigoff. Therefore, no liquids were hauled.

2. The preferred method of closure for all temporary pits will be on-site closure by in-place burial, provided all the criteria in 19.15.17.13.B are met.

On-site burial plan for this location was approved by the Aztec District Office on (2/5/2013). However, since the pit was located in an area of fill on the well pad, it was dug and hauled to Envirotech, Inc. Soil Remedation Facility, #43 Rd 7175 (16 miles south of Bloomfield, NM) on (1/22/2014).

3. The surface owner shall be notified of WPX's proposed closure plan using a means that provides proof of notice (i.e. certified mail/return receipt requested)

<u>WPX notified the SMA of its intent to use a temporary pit and onsite burial in the Surface Use Plan in the well APD. The SMA</u> was notified by email see attached. No return receipt required per BLM: FFO/NMOCD MOU dated 5/4/09.

4. Within six months of the "rig-off" status occurring WPX will ensure that the temporary pit is covered, recontoured and reseeding in progress.

Drill rig-off (6/11/2013). Completion Rig-off (8/1/2013) Pit covered (1/22/2014). Pit area along with unused portions of well pad to be interim reclaimed in accordance with Surface Management Agency requirements in APD-COAs and per <u>BLM:FFO/NMOCD MOU dated 5/4/09.</u>

- 5. Notice of Closure will be given to the Aztec District office between 72 hours and one week of the scheduled closure via email or phone. The notification of closure will include the following:
 - a. Operators Name (WPX)
 - b. Well Name and API Number
 - c. Location (USTR)

The Aztec District Office of NMOCD was notified by email using a format acceptable to the District. Copies of the notification from Abode Contractors on (1/10/2014) is attached.

6. The pit liner shall be removed above "mud level" after stabilization. Removal of the liner will consist of manually or mechanically cutting the liner at the mud level and removing all remaining liner. Care will be taken to remove "all" of the liner (I.e. anchored material). All excessive liner will be disposed of at a licensed disposal facility (probably San Juan Regional Landfill operated by Waste Management under NMED Permit SWM-052426).

The liner to the temporary pit was removed above the "mud level" once stabilized. Removal of the liner consisted of manually cutting the liner and removing all remaining liner material. All liner was disposed of at the San Juan Regional Landfill operated by Waste Management under NMED Permit SWM-052426.

7. Solidification of the remaining pit contents shall be achieved by mixing non-waste containing, earthen material. The solidification process will be accomplished use a combination of natural drying and mechanical mixing. Pit contents will be mixed with non-waste, earthen material to a consistency that is deemed safe and stable. The mixing ratio shall not exceed 3 parts non-waste to 1 part pit contents.

After solidification. the pit contents were completely removed and hauled to Envirotech, Inc. Soil Remedation Facility, #43 Rd 7175 (16 miles south of Bloomfield, NM) on (1/22/2014).

8. A five-point composite sample will be taken underneath the pit liner using sampling tools and all samples tested per 19.15.17.13(B)(1)(b) NMAC. In the event that the criteria are not met (See Table 1), all contents will be handled per 19.15.17.13(B)(1)(a) (i.e. dig and haul to a Division-approved facility). Approval to haul will be requested of the Aztec District office prior to initiation.

<u>A five-point composite sampling was taken from underneath the pit liner using sampling tools and the sample was tested per 19,15.17.13(B)(1)(b) NMAC. Results are shown in Table 1 and lab reports are attached.</u>

| rable 1. Closure enterna for reinporary rits in Non-sensitive Areas with Orbundwater > 100 bgs. | | | | |
|---|-----------------------------------|--------------------|-------------|--|
| Components | Testing Methods | 🗠 Limits (mg/Kg) 🏠 | Pit (mg/Kg) | |
| Benzene | EPA SW-846 Method 8021B or 8260B | 0.2 | < 0.05 | |
| BTEX | EPA SW-846 Method 8021B or 8260B | 50 | < 0.05 | |
| ТРН | EPA SW-846 Method 418.1 | 2500 | 59.9 | |
| GRO/DRO | EPA SW-846 Method 8015M (GRO/DRO) | 500 | 60.9 | |
| Chlorides | EPA SW-846 Method 300.1 | 500 | 51.2 | |

| | for Temporary I | Pits in Non-sensitive | Areas with | Groundwater >100 bgs | |
|--|-----------------|-----------------------|------------|----------------------|--|
| | | | | | |

9. Upon completion of pit removal and testing, the pit area will be backfilled with non-waste earthen material compacted to native conditions to enable effective revegetation for successful evapotranspiration. A minimum of four feet of cover including replacement of one foot of suitable material to establish vegetation, or the background thickness of topsoil, whichever is greater.

<u>Upon completion of pit removal and testing, the pit area was backfilled with non-waste earthen material compacted to native</u> <u>conditions</u>. <u>A minimum of four feet of cover to the extent practical was achieved and the cover included just over a foot of topsoil</u> <u>suitable to establish vegetation</u>.

10. Following cover, the site will be recontoured to meet the Surface Management Agency or surface owner requirements. Recontouring will attempt to match fit, shape, line form, and texture of the surrounding geography. Re-shaping will include drainage control, prevent ponding, and minimize erosion. Natural drainages will be unimpeded and stormwater Best Management Practices (BMPs) will be used to aid in soil stabilization and protection surface water quality.

Following cover, WPX reestablished drainage and contours to approximately match previous topography meeting the Conditions of Approval in the APD and the direction offered by a BLM/USFS inspector. Cover and re-contouring were completed (1/22/2014).

11. Notification will be sent to the Aztec District office when the reclaimed area is seeded. <u>WPX will comply with Surface Management Agency reseeding requirements in the COAs of the APD for the referenced well, per</u> <u>BLM:FFO/NMOCD MOU dated 5/4/09.</u>


12. WPX shall seed the disturbed areas the first growing season after the pit is covered. Seeding will be accomplished via drilling on the contour whenever practical, or by other Division-approved methods. Vegetative cover will equal 70% of the native perennial vegetative cover (un-impacted) consisting of at least three native plant species, including at least one grass, but not including noxious weeds, and maintained that cover through two successive growing seasons. Repeat seeding or planting will be continued until successful vegetative growth occurs. *Note: WPX assumes the seeding stipulations including mix and seeding methods specified by the Surface Management Agency (BLM, BOR, USFS, Tribal, etc.) or Land owner as part of a surface use agreement or APD are Division-approved methods unless notified by the Division of their unacceptability.*

WPX will comply with Surface Management Agency reseeding requirements in the COAs of the APD for the referenced well, per BLM: FFO/NMOCD MOU dated 5/4/09.

13. The temporary pit will be located with a steel marker, no less than four inches in diameter, cemented in a hole three feet deep in the center of the on-site burial upon the abandonment of all wells on the pad. The marker will be flush with the ground to allow access of the active well pad and for safety concerns. The marker will include a threaded collar to be used for future abandonment. The top of the marker will contain a welded steel 12" square plate that indicates the on-site burial of the temporary pit. The plate will be easily removable and a four-foot tall riser will be threaded into the top of the collar marker and welded around the base with the operations information at the time of all wells on the pad abandoned. The information will include Operator Name, Lease Name, Well Name, and number, USTR, and an indicator that the marker is an onsite pit burial location.

No steel marker was used for this pit since the contents and liner were completely removed from the location.

.





Analytical Report

Report Summary

Client: WPX Energy, Inc. Chain Of Custody Number: 16611 Samples Received: 2/13/2014 9:00:00AM Job Number: 04108-0006 Work Order: P402035 Project Name/Location: Chaco 2307-12E #168H

Entire Report Reviewed By:

Tim Cain, Laboratory Manager

Date:

2/21/14

The results in this report apply to the samples submitted to Envirotech's Analytical Laboratory and were analyzed in accordance with the chain of custody document supplied by you, the client, and as such are for your exclusive use only. The results in this report are based on the sample as received unless otherwise noted. Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc. If you have any questions regarding this analytical report, please don't hesitate to contact Envirotech's Laboratory Staff.

| 5796 US Highway 64, Farmington, NM 87401 | Ph (505) 632-0615 | Fx (505) 632-1865 | envirotech-inc.com |
|---|-------------------|-------------------|-------------------------------|
| Three Springs - 65 Mercado Street, Suite 115, Durango, CO 81301 | Ph (970) 259-0615 | Fr (800) 362-1879 | laboratory@envirotech-lnc.com |

Page 1 of 10



| WPX Energy, Inc. | Project Name: | Chaco 2307-12E #168H | |
|----------------------|------------------|----------------------|-----------------|
| PO Box 21218 | Project Number: | 04108-0006 | Reported: |
| Tulsa OK, 74121-1358 | Project Manager. | Buddy Shaw | 21-Feb-14 18:46 |

Analyical Report for Samples

| Client Sample ID | Lab Sample ID | Matrix | Sampled | Received | Container |
|-------------------|---------------|--------|----------|----------|------------------|
| Cuttings Pit Area | P402035-01A | Soil | 02/10/14 | 02/13/14 | Glass Jar, 4 oz. |

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

 5796 US Highway 64, Farmington, NM 87401
 Ph (505) 632-0615
 Fx (505) 632-1865
 Bartinoled Hindcom

 Three Springs - 65, Mercado Street, Suite 115, Durango, CO 81301
 Ph (970) 259-0615
 Fr (800) 362-1879
 Vebratory Canvinced Hindcom

Page 2 of 10 4



.

| WPX Energy, Inc. PO Box 21218 Tulsa OK, 74121-1358 | Proje | et Name: et Number . et Manager: | Chaco 2307-12E #168H 04108-0006 Buddy Shaw | | | | | Reported: 21-Feb-14 18:46 | |
|--|--------|---|--|----------|---------|----------|----------|------------------------------|-------|
| | | | ngs Pit A 35-01 (Se | | | | | | |
| Analyte | Result | Reporting Limit | Units | Dilution | Batch | Prepared | Analyzed | Method | Notes |
| Volatile Organics by EPA 8021 | | | | | | | | | |
| Benzene | ND | 0.05 | mg/kg | 1 | 1407029 | 02/13/14 | 02/19/14 | EPA 8021B | |
| Toluene | ND | 0.05 | mg/kg | 1 | 1407029 | 02/13/14 | 02/19/14 | EPA 8021B | |
| Ethylbenzene | ND | 0.05 | mg/kg | 1 | 1407029 | 02/13/14 | 02/19/14 | EPA 8021B | |
| p,m-Xylene | ND | 0.05 | mg/kģ | 1 | 1407029 | 02/13/14 | 02/19/14 | EPA 8021B | |
| o-Xylene | ND | 0.05 | mg/kg | 1 | 1407029 | 02/13/14 | 02/19/14 | EPA 8021B | |
| Total Xylenes | ND | 0.05 | mg/kg | 1 | 1407029 | 02/13/14 | 02/19/14 | EPA 8021B | |
| Total BTEX | ND | 0.05 | mg/kg | 1 | 1407029 | 02/13/14 | 02/19/14 | EPA 8021B | |
| Surrogate: Bromochicroberzene | | 103 % | 80 | -120 | 1407029 | 02/13/14 | 02/19/14 | EPA 8021B | |
| Surrogate: 1,3-Dichlorobenzerie | | 94.6 % | 80 | -120 | 1407029 | 02/13/14 | 02/19/14 | EPA 8021B | |
| Nonhalogenated Organics by 8015 | | | | | | | | | |
| Gasoline Range Organics (C6-C10) | ND | 4.99 | mg/kg | 1 | 1407029 | 02/13/14 | 02/19/14 | EPA 8015D | |
| Diesel Range Organics (C10-C28) | 60.9 | 30.0 | mg/kg | 1 | 1407028 | 02/13/14 | 02/18/14 | EPA 8015D | |
| Total Petroleum Hydrocarbons by 418.1 | _ | | | | | | | | |
| Total Petroleum Hydrocarbons | 59.9 | 20.0 | mg/kg | ì | 1407032 | 02/14/14 | 02/14/14 | EPA 418.1 | |
| Cation/Anion Analysis | | | | | | | | | |
| Chloride | 51.2 | 9.93 | mg/kg | 1 | 1407027 | 02/13/14 | 02/13/14 | EPA 300.0 | |

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

| 5796 US Highway 64, Farmington, NM 87401 | Ph (505) 632-0615 | Fx (505) 632-1865 | envirotedreinacom |
|---|-------------------|-------------------|------------------------------|
| Three Springs - 65 Mercado Street, Suite 115, Durango, CO 81301 | Ph (970) 259-0615 | Fr (800) 362-1879 | laboratory@envirotedn-inccom |

Page 3 of 10



٠

| WPX Energy, Inc. PO Box 21218 Tul sa OK, 74121-1358 | Proj | eet Name: eet Number: eet Manager: | 0- | haco 2307-12 4108-0006 uddy Shaw | 2E #168H | | | | Repor 21-Feb-14 | |
|---|---------|--|-------|--|------------------|-------------|----------------|-----|--------------------|-------|
| | | Organics b virotech 4 | - | - | • | trol | | | | |
| Analyte | Result | Reporting Limit | Units | Spike Level | Source Result | %REC | %REC Limits | rpd | RPD Limit | Notes |
| Batch 1407029 - Purge and Trap EP | A 5030A | | | | | | · | | | |
| Blank (1407029-BLK1) | | Prepared: 13-Feb-14 Analyzed: 18-Feb-14 | | | | | | | | |
| Benzene | ND | 0.05 | mg/kg | | | | | | | · |
| Toluene | ND | 0,05 | • | | | | | | | |
| Ethylbenzene | ŅD | 0.05 | • | | | | | | | |
| p,m-Xylene | ND | 0.05 | • | | | | | | | |
| o-Xylene | ND | 0.05 | • | | | | | | | |
| Total Xylenes | ND | 0.05 | • | | | | | | | |
| Total BTEX | ND | 0.05 | | | | | | | | |
| Surrogale: 1,3-Dichlorobenzene | 47.9 | | ug/L | 50.0 | | 95.7 | 80-120 | | | |
| Surrogate: Bromochlorobenzene | 50.3 | | " | 50.0 | | 101 | 80-120 | | | |
| Duplicate (1407029-DUP1) | Sour | ce: P402032- | 01 | Prepared: 1 | 3-Feb-14 | Analyzed: 1 | 18-Feb-14 | | | |
| Benzene | ND | 0.05 | mg/kg | | ND | | | | 30 | |
| Toluene | ND | 0.05 | • | | ND | | | | 30 | |
| Ethylbenzene | ŅD | 0.05 | • | | ND | | | | 30 | |
| p.m-Xylene | ND | 0.05 | • | | ND | | | | 30 | |
| o-Xylene | , ND | 0.05 | • | | ND , | | | | 30 | |
| Surrogate: 1,3-Dichlorobenžene | 48.4 | | uġ/L | 50.0 | | 96.9 | 80-120 | | | · · |
| Surrogáta: Bromochlorobanzana | 50.1 | | | 50.0 | | 100 | 80-120 | | | |
| Matrix Spikë (1407029-MS1) | Souir | ce: P402032- | 01 | Prepared: 1 | 3-Feb-14 / | Analyzed: 1 | 8-Feb-14 | | | |
| Benzene | 50.9 | | ug/L | 50.0 | ND | 102 | 39-150 | | | |
| Toluene | 51.1 | | | 50.0 | ND | 102 | 46-148 | | | |
| Ethylbenzene | 50.8 | | • | 50.0 | ŇD | 102 | 32-160 | | | |
| p.m-Xylene | 102 | | | 100 | ND | 102 | 46-148 | | | |
| o-Xylene | 51.2 | | • | 50.0 | ND | 102 | 46-148 | | | |
| Surrogate: 1,3-Dichlorobenzene | 50.0 | | н | 50.0 | | 100 | 80-120 | | | |
| Surrogate: Bromochlorobenzene | 51.4 | | n | 50.0 | | 103 | 80-120 | | | |

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

| 5796 US Highway 64, Farmington, NM 87401 | Ph (505) 632-0615 Fx (505) 632-1865 | enviroled+inecom |
|---|-------------------------------------|---------------------------|
| Three Springs - 65 Mercado Street, Suite 115, Durango, CO 81301 | Ph (970) 259-0615 Fr (800) 362-1879 | Hornory Denvioted Andron. |
| | | Page 4 of 10 |



· · ·

| WPX Energy, Inc. PO Box 21218 Tulsa OK, 74121-1358 | Pro | eet Name: eet Number: eet Manager: | 0 | haco 2307-12 4108-0006 uddy Shaw | E #168H | | | | Report 21-Fcb-14 | |
|--|---------|--|-------|--|------------------|-------------|----------------|------|---------------------|-------|
| | Ū | enated Org | • | - | | ntrol | | | | |
| Ańalyte | Result | Reporting Limit | Units | Spike Level | Source Result | .%REC | %REC Limits | RPD | RPD Limit | Notes |
| atch 1407028 - DRO Extraction EP | A 3550C | | | | | | · · · | | | |
| Bank (1407028-BLK1) | | | | Prépared: 1 | 3-Feb-14 | Analyzed: 1 | 8-Feb-14 | | | |
| iesel Range Organics (C10-C28) | ND | 29.9 | mg/kg | | | | | | | |
| uplicate (1407028-DUP1) | Soui | ce: P402032- | 01 | Prepared: 1 | 3-Feb-14 | Ánalyzed: 1 | 8-Feb-14 | | | |
| nipilcate (140/023-1/0P1) | | | | | | | | | 30 | |
| | 945 | 30.0 | mg/kg | | 919 | | | 2.74 | 20 | |
| Liesel Range Organics (C10-C28) | | 30.0 | | Prepared: 1 | | Analyzéd: 1 | 8-Feb-14 | 2.14 | 30 | |

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

| 5796 US Highway 64. Farmington, NM 87401 | Ph (505) 632-0615 Fx (505) 632-1865 | envirotech-incicom |
|---|-------------------------------------|--------------------------------|
| Three Springs - 65 Mercado Street, Suite 115, Durañgo, CO 81301 | Ph (970) 259-0615 Fr (800) 362-1879 | ▲ Aboratory @envirotech+inccom |

> Page 5 of 10



.

| WPX Energy, Inc. PO Box 21218 Tulsa OK, 74121-1358 | Pro | jeet Name: jeet Number: jeet Manager: | 0 | haco 2307-12 1108-0006 uddy Shaw | E #168़H | | | | Repor 21-Feb-14 | |
|--|-----------|---|-------|--|------------------|-------------|----------------|-----|--------------------|-------|
| | U | enated Org avirotech 2 | • | - | • | ntrol | | | | |
| Analyte | Result | Reporting Limit | Units | Spike Level | Source Result | %REC | %REC Limits | RPD | RPD Limit | Notes |
| Batch 1407029 - Purge and Trap EP. | A 5030A . | | | | | | | | | |
| Blank (1407029-BLK1) | | | | Prepared: 1 | 3-Feb-14 | Analyzed: 1 | 8-Feb-14 | | | |
| Gasoline Range Organics (C6-C10) | ND | 5,00 | mg/kg | | | | | | | |
| Duplicate (1407029-DUP1) | Sou | rce: P402032- | 01 | Prepared: 1 | 3-Feb-14 | Analyzed: 1 | 8-Feb-14 | | | |
| Gasoline Range Organics (C6-C10) | ND | 4.99 | mg/kg | | ND | | | | 30 | |
| Matrix Spike (1407029-MS1) | Sou | rce: P402032- | 01 | Prepared: 1 | 3-Feb-14 | Analyzed: 1 | 8-Feb-14 | | | |
| Gasoline Range Organics (C6-C10) | 0.49 | | mg/L | 0.450 | ND | 108 | 75-125 | | | |

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

| 5796 US Highway 64, Farmington, HM 87401 | Ph (505) 632-0615 | Fx (505) 632-1865 | envioledianarom |
|---|-------------------|-------------------|--------------------------------|
| Three Springs - 65 Mercado Street, Suite 115, Durango, CO 81301 | Ph (970) 259-0615 | Fr (800) 362-1879 | Subpratory@envirotech*inccom > |

₩ Page 6 of 10



.

| WPX Energy, Inc. PO Box 21218 Tulsa OK, 74121-1358 | Pro | jeet Name: jeet Numb er: jeet Manager: | 0 | haco 2307-12 4108-0006 uddy Shaw | E #168H | | | | Report 21-Feb-14 | |
|--|---------------------|---|-------|--|------------------|-----------|----------------|------|---------------------|-------|
| | Total Petrole Ei | eum Hydrod nvirotech 4 | | • | | Control | | | | |
| Analyte | Kesult | Reporting Limit | Units | Spike Level | Source Result | .%REC | %REC Limits | RPD | RPD Limit | Notes |
| Batch 1407032 - 418 Freen Extraction | | | | | | | | | | |
| Blank (1497032-BLK1) | | | | Prépared & | Analyzed: | 14-Feb-14 | | | | |
| Total Petroleum Hydrocarbons | ND | 20.0 | mg/kg | | | | | | | |
| Duplicate (1407032-DUP1) | Sou | rce: P402035- | 01 | Prepared & | Analyzed: | 14-Fcb-14 | | | | |
| Total Petroleum Hydrocarbons | 67.8 | 20.0 | mg/kg | | 59.9 | | | 12.5 | 30 | |
| Matríx Spike (1407032-MS1) | Sou | rce: P402035- | 01 | Prepared & Analyzed: 14-Feb-14 | | | | | | |
| Total Petroleum Hydrocarbons | 1820 | 19.9 | mg/kg | 1990 | 59.9 | 88.4 | 80-120 | | | |

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

| | 5796 US Highway 64. Farmington, NM 87401 | Ph (505) 632-0615 | Fx (505) 632-1865 | envirotech+incrom |
|---|---|-------------------|-------------------|----------------------------------|
| - | Three Springs • 65 Mercado Street, Suite 115, Durango, CO 81301 | Ph (970) 259-0615 | Fr (800) 362-1879 | Liberatory@envirotech=inctcom)s. |
| | | | | |

🗄 Page 7 of 10.



| WPX Energy, Inc. PO Box 21218 Tulsa OK, 74121-1358 | Proj | eet Name: eet Number: eet Manager: | 04 | haco 2307-12 1108-0006 uddy Shaw | E #168H | | | | Report 21-Feb-14 | |
|--|--------|--|--------|--|------------------|-----------|----------------|------|---------------------|---|
| | | on/Anion A | • | | | | | | <u></u> 440 | |
| | L11 | virotech A | Anaiyu | | atory | | · | | | |
| Analyte | Result | Reporting Limit | Units. | Spike Level | Source Result | %REC | %REC Limits | RPD | RPD Limit | Notes |
| Batch 1407027 - Anion Extraction EPA | 300.0 | | | | _ | | | | | |
| Blank'(1407027-BLK1) | 500.0 | | | Prepared & | Analyzed | 13-Feb-14 | | | | |
| Chloride | ND | 9.96 | mg/kg | | | | | | | |
| LCS (1407027-BS1) | | | | Prepared & | : Analyzed: | 13-Fcb-14 | | | | |
| Chloride | 510 | 9.92 | mg/kg | 496 | | 103 | 90-110 | | | |
| Matrix Spike (1407027-MS1) | Sour | Source: P402032-01 Prepared & Analyzed: | | | | 13-Feb-14 | | | | |
| Chloride | 650 | 9.96 | mg/kg | 498 | 150 | 100 | 80-120 | | | · · • • • • • • • • • • • • • • • • • • |
| Matrix Spike Dup (1407627-MSD1) | Sour | ce: P402032- | 01 | 11 Prepared & Analyzed: 13-Feb-14 | | | | | | |
| Chloride | ,660 | 9.97 | mg/kg | 499 | 150 | 102 | 80-120 | 1.54 | 20 | |

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

| 5796 US Highway 64, Farmington, NM 87401 | Ph (505) 632-0615 Fx (505) 632-1865 | envirolech inccom. |
|---|-------------------------------------|--------------------------------|
| Three Springs • 65 Mercado Street, Suite 115, Durango, CO 81301 | Ph (970) 259-0615 Fr (800) 362-1879 | A laboratory@envirotech=inccom |

Page 8 of 10



| WPX Energy, Inc. | Project Name: | Chaco 2307-12E #168H | |
|----------------------|------------------|----------------------|-----------------|
| PO Box 21218 | Project Number: | 04108-0006 | Reported: |
| Tulsa OK, 74121-1358 | Project Manager: | Buddy Shaw | 21-Feb-14 18:46 |

Notes and Definitions

- SPK1 The spike recovery for this QC sample is outside of control limits.
- DET Analyte DETECTED
- ND Analyte NOT DETECTED at or above the reporting limit
- NR Not Reported
- dry. Sample results reported on a dry weight basis
- RPD Relative Percent Difference

Partial or incomplete reproduction of this report is prohibited, unless approved by Envirotech, Inc.

5796 US Highway 64, Farmington, NM 87401

Three Springs - 65 Mercado Street, Suite 115, Durango, CO 81301

Ph (505) 632-0615 Fx (505) 632-1865 Ph (970) 259-0615 Fr (800) 362-1879 envirotethfination laboratory@envirotech-inctcom

Page 9 of 10

CHAIN OF CUSTODY RECORD 16611

| Client: <i>UPX</i> Energy Email results to: | × | | bject Name / Location | | E # | 168 | H | | | | | <u>.</u> | ANAL | YSIS | / PA | RAM | ETEF | RS | | | |
|---|----------------|----------------|------------------------|-----------|---------------------|------------|----------------------|---------|-------------------|--------------------|-------------------|----------------|-------|---------------|----------------|-------------|----------|---------|-------------|-------------|---------------|
| buddy, Show Qup | xenergy. | Sa | mpler Name: Bob Lee | | | | | | 8015) | 1 8021) | 8260) | n . | | | | | | | | | |
| Client Phone No.: 505-33310 | | Çli : | ent No.: 0410 | 8-0 | bD6 | | | | TPH (Method 8015) | BTEX (Method 8021) | VOC (Method 8260) | Cation / Anion | | TCLP with H/P | CO Table 910-1 | TPH (418.1) | RIDE | | | Sample Cool | Sample Intact |
| Sample No./ Identification | Sample Date | Sample Time | Lab No. | | Volume Intainers | PI HNO3 | eservativ | 0: i | ТРН () | BTEX | VOC (| | RCI | TCLP | со та |) HdT | CHLORIDE | | | Sampl | Samp |
| Catting Pit Area | 21 2/14 | 2:45 pm | P402035-0 | 1 | 402 | - | | | V | / | | | | | | / | | | | Y | y: |
| | | | - | | | | | | | | : | _ | • | | | | | | | | |
| | | | | | | <u> </u> | | | | | | | | | - | | | | | | |
| | | | <u></u> | | | | | | | | | _ | | <u>.</u> | | | | | | | + |
| | | | | | | | | | | | | | | | | | | | | | |
| · · · | | | | | | | | | | | | | | | | | | | | | <u> </u> |
| | | , | | | | | | | | | | | | | | | | | | | |
| Relinquished by: (Signature) | She/5 | / | | Date | Time 9:00 | | ived by | | 4 | Ż | | | 2 | | | | | | Dat 2/13 | | Time 900 |
| Relinquished by: (Signature) | | | | | | Rece | ived by | /: (Sig | matu | re) | | | | | | | | | | | |
| Sample Matrix Soil 🕅 Solid 🔲 Studge 🗌 | Aqueous [|] Other [] | ľ | | | | | | | | | | | | | | | | | | |
| Sample(s) dropped off after | r hours to se | cure drop.o | ff area. | 30 | P N V And | alytic | | e C | : h lory | | | 20. | 6 | | | | | | | | |
| 5795.US Highway 6 | 4 • Farmingt | on, NM 8740 | 01 • 505-632-0615 • 1 | fhree Spi | ings • 65 | Merca | do [:] Stre | et, Sui | te 11 | 5. Du | rango | <u>co</u> | 31301 | labo | prațoi | γ@er | virote | ech-ind | Pag | e 10 | of/10 |

| | Willia | П́я. | | | TEMPO | ORARY F | PIT IN | NSPE | CTI | ON REPO | RT | |
|-----------|----------------|----------------|------------------------|----------------|-------------------------|------------------------------|--------------------|-----------------------|-------|--|--|-----------------------------------|
| Well Name | CH | ACO 2307-12E#1 | 68H | Field Name | | Lybrook | , | API# | | 30-039-31173 | Report # | 1 |
| Location | | | | County | | Rio Arriba | <u>.</u> | State | | NM | Rpt Date | 5/8/2013 |
| Date | Report Type | Inspector | Liner Intact Y/N | Fenced Y/N | Slopes Intact Y/N | Adequate Freeboard Y/N | Oil Free Y/N | Flare Liquid Y/ | Free | Co | omment | |
| 5/8/13 | Daily | | | | | | | | | CLOSED LOOP, NO | LEAKS, NO S | PILLS. |
| 5/9/13 | Daily | | | | | | | | | CLOSED LOOP, NO | LEAKS, NO S | PILLS. |
| 5/10/13 | Daily | | | | | | | | | CLOSED LOOP, NO | LEAKS, NO S | PILLS. |
| 5/11/13 | Daily | | | | | | | | | CLOSED LOOP, NO | LEAKS, NO S | PILLS. |
| 5/12/13 | Daily | | | | | | | | | CLOSED LOOP, NO | LEAKS, NO S | PILLS. |
| 5/13/13 | Daily | | | | | | | 1 | | CLOSED LOOP, NO | LEAKS, NO S | PILLS. |
| 5/14/13 | Daily | | | | | | | | | CLOSED LOOP, NO | LEAKS, NO S | PILLS. |
| 54540 | | | | | | | | | | CLOSED LOOP, SF BASED MUD @ 5:0 SUCTION HOSE HA MUD UNDER THE L ON LOCATION & S RECOVERED 80 Bb | 0 PM, 5/14/13. .D A HOLE & P INER. ALL CON SS WATER TRI | #2 PUMP JMPED TAINED JCK |
| 5/15/13 | Daily | | | | | | | | | PIT. | | |
| 5/16/13 | Daily | | | | | l | <u> </u> | | | CLOSED LOOP, NO | | |
| 5/17/13 | Daily | | | | | | | | | CLOSED LOOP, NO | · · · · · · · · · · · · · · · · · · · | |
| 5/18/13 | Daily | | | | | | | | | CLOSED LOOP, NO | | |
| 5/19/13 | Daily | | L | | | | ┣━━ | <u> </u> | | CLOSED LOOP, NO | | |
| 5/20/13 | Daily | | | | | | | | | CLOSED LOOP, NO | LEAKS, NO S | PILLS. |
| 5/21/13 | Daily | | | | | | | | | CLOSED LOOP, NO | LEAKS, NO S | PILLS. |
| 5/22/13 | Daily | | | | | | L | | | CLOSED LOOP, NO | LEAKS, SPILL | S |
| 5/23/13 | Daily | | | | | | ļ | | | CLOSED LOOP, NO | LEAKS, NO S | PILLS. |
| 5/24/13 | Daily | | | | | | L | | | CLOSED LOOP, NO | LEAKS, NO S | PILLS. |
| 5/25/13 | Daily | | | | | | | | | CLOSED LOOP, NO | LEAKS, NO S | PILLS. |
| 5/26/13 | Daily | | | | | | L | | | CLOSED LOOP, NO | LEAKS, NO S | PILLS. |
| 5/27/13 | Daily | | | | | | | | | CLOSED LOOP, NO | LEAKS, NO S | PILLS. |
| 5/28/13 | Daily | | | | | | | | | CLOSED LOOP, NO | LEAKS, NO S | PILLS. |
| 5/29/13 | Daily | | | | | | | | | CLOSED LOOP, NO | LEAKS, NO S | PILLS. |
| 5/30/13 | Daily | | | | | | | | | CLOSED LOOP, NO | LEAKS, NO S | PILLS. |
| 5/31/13 | Daily | | | | | | | | | CLOSED LOOP, NO | LEAKS, NO S | PILLS |
| 6/1/13 | Daily | | | | | | | | | CLOSED LOOP, NO | LEAKS, NO S | PILLS. |
| 6/2/13 | Daily | | | | | | | | | CLOSED LOOP, NO | LEAKS, NO S | PILLS. |
| 6/3/13 | Daily | | | | | | | | | CLOSED LOOP, NO | LEAKS, NO S | PILLS. |
| 6/4/13 | Daily | | | | | | | | | CLOSED LOOP, NO | LEAKS, NO S | PILLS |
| 6/5/13 | Daily | | | | | | | | | CLOSED LOOP, NO | LEAKS, NO S | PILLS. |
| 6/6/13 | Daily | | | | | | | | | CLOSED LOOP, NO | LEAKS, NO S | PILLS. |
| 6/7/13 | Daily | | | | | | | | | CLOSED LOOP, NO | LEAKS, NO S | PILLS. |
| 6/8/13 | Daily | | | | | | | | | NO LEAKS, NO SP | LLS / CLOSED | LOOP |
| 6/9/13 | Daily | | | | | | | | | CLOSED LOOP, NO | LEAKS, NO S | PILLS. |
| 6/10/13 | Daily | | | | | | | 1 | | CLOSED LOOP, NO | LEAKS, NO S | PILLS. |
| 6/11/13 | Daily | | | | | | | | | CLOSED LOOP, NO | LEAKS, NO S | PILLS. |
| 6/12/13 | Daily | | | | | | <u> </u> | | | CLOSED LOOP, NO | · · · · · | |
| 6/13/13 | Daily | | | | | | | | | CLOSED LOOP / N | D LEAKS NO S | PILLS. |
| | - | · | 20 | 01-2009 WellEz | Information M a | anagement, LLC. All r | rights rese | rved ver. 111 | 709jc | | | |

. . . .

District I 1625 N. French Drive, Hobbs, NM 88240 Phone (575) 393-6161 Fax (575) 393-0720

District II 811 S. First Street, Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Road, Aztec, NM 87410 Phone (505) 334-6178 Fax: (505) 334-6170

District IV 1220 S. St. Francis Drive, Santa Fe, NM 87505 Phone: (505) 475-3460 Fax: (505) 476-3462

State of New Mexico Energy, Minerals & Natural Resources Department

Form C-102 Revised August 1, 2011

Submit one copy to Appropriate District Office

AMENDED REPORT


OIL CONSERVATION DIVISION 1220 South St. Francis Drive Santa Fe, NM 87505

WELL LOCATION AND ACREAGE DEDICATION PLAT API Number Pool Code 'Pool Name 42289 LYBROOK GALLUP Property Code Property Name. Well Number CHACO 2307-12E '168H OGRID No. Elevation [®]Operator Name 120782 WPX ENERGY PRODUCTION, LLC 7036

10 Surface Location

| , | | | | | 00 1000 | | | | |
|--------------------|---------------|-----------------|---------------------|---------|-------------------------------|----------------------------------|-------------------------|------------------------|---------------|
| UL OF LOL NO. E | Section 12 | Township 23N | Range 7W | Lot lon | Feet from the | North/South line | Feet from the 303 | East/West line WEST | RIO ARRIBA |
| | | 1 | ¹¹ Botto | m Hole | Location I | f Different | From Surfac | e | |
| UL or lot no. | Section | Township | Range | Lot Idn | Feet from the | North/South line | Feet from the | East/West line | County |
| D | 11 | NE2 | 7W | 2 | 563 | NORTH | 379 | WEST | RIO ARRIBA |
| 12 Dedicated Acres | | 155.09 | Acres | | ¹³ Joint or Infill | ¹⁴ Consolidation Code | ¹⁵ Order No. | | |
| _ | N/2 | | Section | 11 | | | | | |

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION



| From: | Johnny [johnny@adobecontractorsinc.com] |
|----------|--|
| Sent: | Friday, January 10, 2014 11:59 AM |
| То: | Brandon Powell (NMOCD) |
| Cc: | Granillo, Lacey; Riley, Heather |
| Subject: | Notice of pit closure on WPX location Chaco 2307-12E #168H |

Brandon,

•

.

We will be closing this pit for WPX around the middle of next week. Please let me know if you have any questions.

Thank you,

Johnny R. Stinson General Manager Adobe Contractors Inc. Office: 505-632-1486 Fax: 505-632-9807 Mobile: 505-320-6076 johnny@adobecontractorsinc.com

| Submit To Appropri Two Copies District 1 | ate District O | Office | | - Ene | erav | State of Ne Minerals an | | | | Souraas | | | | | | | Form C-105 ugust 1, 2011 |
|--|---------------------|----------------------|------------|------------------|-----------|-------------------------------|---------------------|-----------------------|------------------|--------------|-------|--|---|---|--------------------|--------------------------|-----------------------------|
| 1625 N. French Dr., District II | | | | Lin | | | | | | sources | | 1. WELL 30-039-31 | | NO. | | 5 V 13 CU 7 1 | ugust 1, 2011 |
| 811 S. First St., Arte District III | | | | | | Dil Conserva 220 South S | | | | | | 2. Type of L | ease | | | | |
| 1000 Rio Brazos Rd District IV | | | | | | Santa Fe, 1 | NM 8 | 8750: | 5 | | | 3. State Oil | | FEE | | FED/IND | IAN |
| 1220 S. St. Francis I | | | | | | | | | | | | NMSF 07836 | 52 | | | ered | |
| 4. Reason for filir | | - HON C | <u>R R</u> | RECC | MPL | ETION RE | POI | RT / | | LOG | | 5. Lease Nan | anony desire, on co | Contraction of the second s | | remotion we not a series | |
| | - | RT (Fill in b | oxes # | 1 throu | gh #31 | for State and Fe | e well | s only |) | | | Chaco 2307-1 6. Well Num | 2E | | | | i |
| C-144 CLOS | | | | | - | | | • | | and #32 and | 1/or | | 001. 1 | 10011 | | | |
| #33; attach this an | d the plat to | the C-144 c | losure | e report | in accor | rdance with 19.1 | 5.17. | 13.K N | VMA | C) | | | | | | | |
| 7. Type of Compl | 'ELL 🔲 W | VORKOVE | R 🗌 | DEEPE | ENING | | K 🔲 | DIFF | EREI | NT RESERV | VOIF | | | | | | |
| 8. Name of Operat WPX Energy Prod | or uction, LLC | 2 | | | | | | | | | | 9. OGRID 120782 | - | | | | |
| 10. Address of Op | erator | | | | | | | | | | | 11. Pool name or Wildcat Lybrook/Gallup | | | | | |
| PO Box 640 / 721 | Unit Ltr | Section | | Townsl | hip | Range | Lot | | | Feet from | the | N/S Line | | t from the | E/W | Line | County |
| Surface: | | | | | | | | | | += | | | | | | · · · | |
| BH: | | | | | | | | | | | | | | | | | |
| 13. Date Spudded | 14. Date | T.D. Reache | ed | 15. D 6/11/ | | Released | • | | 16. | Date Comp | leted | I (Ready to Prod | luce) | | 7. Eleva T, GR, | | and RKB, |
| 18. Total Measured | Depth of V | Well | | 19. P | lug Bac | k Measured Dep | oth | | 20. | Was Direct | tiona | al Survey Made | ? | 21. Ty | be Electi | ric and O | her Logs Run |
| 22. Producing Inter | rval(s), of th | nis completi | on - To | op, Bott | tom, Na | me | | | 1 | | | | | <u> </u> | | | |
| 23. | | | | | | CORD (Rep | oort a | all str | | | ell) | | | | | | |
| CASING SIZ | <u>E</u> | WEIGHT | LB./F | <u>T.</u> | | DEPTH SET | | | HO | LE SIZE | | CEMENTIN | G RE | CORD | A | MOUNT | PULLED |
| | | | | - | | <u> </u> | _ | | | | | | | | | | _ |
| | | | | | | | - | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | |
| 24. | | | | | LINE | ER RECORD | | | | | 25. | | | NG REC | | | |
| SIZE | ТОР | | BOT | ГОМ | | SACKS CEM | ENT | SCF | REEN | 1 | SIZ | Z <u>E</u> | D | EPTH SE | T | PACK | ER SET |
| | | | <u> </u> | | | | | | | | | | | | | | |
| 26. Perforation r | ecord (interv | val, size, and | 1 num | ber) | | I | | | | | | ACTURE, CE | | | | | |
| | | | | | | | | DEI | PTH | NTERVAL | , | AMOUNT A | ND I | <u> KIND MA</u> | TERIA | L USED | |
| | | | | | | | | | | | | - | | | | | |
| | | | | | ···· | | | | | | | | | | | | _ |
| 28. Date First Producti | 00 | Dro | ductic | n Meth | od (Elo | wing, gas lift, pi | | DUC | | | | Well Status | Pro | d or Shut | _in) | | ·· · |
| Date Prist Products | on | | auone | ni wietii | 100 (1 10 | 1111 <u>8, 8</u> 05 191, pt | ampin | 15 - 012 | e un | a type pump, | , | , wen statu | , | a. or ona | ing . | | |
| Date of Test | Hours Tes | sted | Chok | ke Size | | Prod'n For Test Period | | Oil | - Bbl | | Gas | s - MCF | Ŵ | ater - Bbl | | Gas - C |)il Ratio |
| Flow Tubing Press. | Casing Pr | ressure | | ulated 2 Rate | 4- | Oil - Bbl. | | | Gas - | MCF | 1 | Water - Bbl. | | Oil Gra | wity - A | .PI - <i>(Cor</i> | r.) |
| 29. Disposition of (| Gas <i>(Sold, u</i> | ised for fuel, | vente | d, etc.) | | | | | | | | | 30. | Cest Witne | essed By | / | |
| 31. List Attachmen | ts | | | | | | | | | | | | | | | | |
| 32. If a temporary j | | | | | | | | | oit. | | | | | | | | |
| 33. If an on-site bu | rial was use | ed at the wel | l, repo | ort the ex | xact loc | ation of the on-s Latitude | | irial: 36.242 | 233 | | | Longitude | - | 107.53485 | ; | NAD 19 | 983 |
| <i>I hereby certify</i> Signature: | that the i | informatio | on sh | F | Printed | | <i>forn</i> rk H | <i>n is tr</i> eil | <i>че с</i> Т | itle: Reg | gula | | f my | knowle | | | |
| ∟ <u>IV</u> ⊻ | <u>~qf</u> | . <u> </u> | | £ | 2-man | <u></u> | | unu | <u>••</u> PX | unorgy.ot | | | | | -+ | | |

| From: | Johnny [johnny@adobecontractorsinc.com] |
|----------|---|
| Sent: | Friday, January 10, 2014 12:03 PM |
| То: | <u>rmckee@blm.gov</u> (Bureau of Land Management) |
| Cc: | Granillo, Lacey; Riley, Heather |
| Subject: | Pit closure on WPX location Chaco 2307-12E #168H |


Randy,

.

We will be closing this pit around the middle of next week for WPX. We will have to haul the contents of the pit, drill cuttings, out to Envirotech. We will not be performing any other reclamation at this time due to WPX having plans to drill another well on this pad sometime this spring. Please contact me if you have any questions concerning this.

Thank you,

Johnny R. Stinson General Manager Adobe Contractors Inc. Office: 505-632-1486 Fax: 505-632-9807 Mobile: 505-320-6076 johnny@adobecontractorsinc.com



No pit marker for the Chaco 2307-12E #168H was used since the contents and liner were completely removed and hauled to the Envirotech, Inc. Soil Remedation Facility, #43 Rd 7175 (16 miles south of Bloomfield, NM).

OIL CONS. DIV DIST. 3

APR 11 2014

| | | | • • | | | | | | | APR |
|------------|-------------|---|---------------|-------------------------|------------------------------|--------------------|---------------------------------|--|--|-------------------------------------|
| , | | | • | | | | | | | |
| | Williams. | - | | MPOR/ | ARY PIT | INSP | ECTION | REPORT | | |
| Mell Nam e | CHACO 23 | 07-12E#168H | Field Nam e | | Lybrook | | API# | 30-039-31173 | Report ₽ | 1 |
| ocation | | | County | | Rio Amba | | State | NM | Rot Date | 5/8/201 |
| | | | | | I | | | 1 | | 1 |
| Date | Report Type | Liner Intact Y/N | Fenced Y/N | Slopes Intact Y/N | Adequate Freeboard Y/N | Oil Free Y/N | Flare Pit Liquid Free Y/N | Con | ament | |
| 5/8/13 | Daity | $\mathbf{Y}^{i} \rightarrow e^{i \mathbf{Y}^{i}}$ | Ϋ́Υ | Y | Y | Y | Y | TEMP PIT, NO LEAKS | , NO SFILLS | |
| 5/9/13 | Daily | Y | _ ` Y | Y | : Y | Y | Y | TEMP PIT, NO LEAKS | , NO SPILLS. | |
| 5/10/13 | Daily | Y , 11 | Y | Y | Y | Y | Y | TEMP PT, NO LEAKS | NO SPILLS | |
| 5/11/13 | Daily | Y | ' ` Y | Y | , Y | Y | Y | TEMP PIT, NO LEAKS | NO SPILLS | |
| 5/12/13 | Daily | • • | : Y | Y | Y | Y | Y | TEMP PIT, NO LEAKS | , NO SPILLS. | |
| 5/13/13 | Daily | Y. | Υ Υ | Y | · Y | Y | Y | TEMP PIT, NO LEAKS | , NO SPILLS. | |
| 5/14/13 | Daily | Y | Ŷ | Y | Y | Y | Y | TEMP PIT, NO LEAKS | · | |
| | | | | | | | | CLOSED LOOP, SFIL BASEDMID @ 5:00 SUCTION HOSE HAD MUD UNDER THE LIN ON LOCATION & SSS RECOVERED 80 Bbl 8 | PM, 5/14/13. A HOLE & P BR. A.L. CON 5 WATER TR | #2. PUMP UMPED ITAINED UKK |
| 5/15/13 | Daily | Y | Y | Y | Y | Y | Y | PT. | | 10 1000 |
| 5/16/13 | Daity | Y | Y | Y | Y | Y | Y | TEMP PIT, NO LEAKS | NO SPILLS. | |
| 5/17/13 | Daily | 1 . Y | Y | Y | Y | Y | Y | TEMP PIL, NO LEAKS | | |
| 5/18/13 | Daily | Y | ·Υ | Y | Y | Y | Y | TEMP PIT, NO LEAKS | , NO SPILLS. | |
| 5/19/13 | Daily | · Y · · / | Y | Y | Y | Y | Y | TEMP PIT, NO LEAKS | NO SPILLS. | |
| 5/20/13 | Daily | . Y | Y | Y | Y | Y | Y | TEMP PIF, NO LEAKS | NO SPILLS. | |
| 5/21/13 | Daily | Y | Y | Y | Y | Y | Y | TEMP PIT, NO LEAKS | | |
| 5/22/13 | Daily | Y | Y | Y | Y | Y | Y | TEMP PIT, NO LEAKS | | |
| 5/23/13 | Daily | Υ, Y | Y | Y | ~ Y | Y | Y | TEMP PIF, NO LEAKS | | |
| 5/24/13 | Daily | Y | Y | Y | Y | Y | Y | TEMP PIT, NO LEAKS | | |
| 5/25/13 | Daily | Y | Y | Y | Y | Y | Ŷ | TEMP PIT, NO LEAKS | | |
| 5/26/13 | Daity | Y | Y | - Y | Y | Y | Y | TEMP PIC, NO LEAKS | | |
| 5/27/13 | Daily | Y | Ŷ | Y | Y | Ŷ | Y | TEMP PIT, NO LEAKS | | |
| 5/28/13 | Daily | Y | Ŷ | Y | Y | Y | Y | TEMP PT, NO LEAKS | | |
| 5/29/13 | Daily | Y | Y | Y | Y | Y | Y | TEMP PIT, NO LEAKS | | |
| 5/30/13 | Daily | Y | Υ | Y | Y | Y | Y | TEMP PIT, NO LEAKS | • • • | |
| 5/31/13 | Daily | Y | · Y | Y | Y | Y Y | Y | TEMP FIT, NO LEAKS | | |
| 6/1/13 | Daily | Y | Υ | Ŷ | Y | Y | Y | TEMP PT, NO LEAKS | • | |
| 6/2/13 | Daily | Y | Y | Y | Y | Y | Y | TEMP PT, NO LEAKS | - | |
| 6/3/13 | Daily | Y | · Y | Y | Y | Y | Y | TEMP PIT, NO LEAKS | · · · · · · · · · · · · · · · · · · · | |
| 6/4/13 | Daily | Y | Y Y | Y | Y | Y | Y | TEMP PIF, NO LEAKS | | |
| 6/5/13 | Daily | Y | Y | Y | Y | Y Y | Y | TEMP PIT, NO LEAKS | | |
| 6/6/13 | Daily | Y | Y | Y | Y | Y | Y | TEMP PIT, NO LEAKS | | |
| 6/7/13 | Daily | Y | Y | Y | Ŷ | Y | Y | TEMP PIT, NO LEAKS | | |
| 6/8/13 | Daily | Т | Ŷ | Y | Y | Y | Ŷ | TEMP PIF, NO LEAKS | | |
| 6/9/13 | Daily | Y | Υ · | Y | Y | Y | Y | TEMP PT, NO LEAKS | - | |
| 6/10/13 | Daily | Y | Y | Y | Y | Y | Y | TEMP PIT, NO LEAKS | | |
| 6/11/13 | Daty | Y Y | Ŷ | Y | Y | Y Y | Y | TEMP PIT, NO LEAKS | | |
| 6/12/13 | Daty | Y. | Ŷ | Y | Y | Y | Y | TEMP PIT, NO LEAKS | | |
| | | · · | - | • | | 1 | | | | - |

.

e.,