



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONS. DIV.

Date of Test 4-24-14 Operator Elm Ridge API #30-0 39-05343
Property Name AX: Packed Well No. 2 Location: Unit 19 Township 24 Range 4
Well Status(Shut-In or Producing) Initial PSI: Tubing 58 Intermediate N/A Casing 124 Bradenhead 123

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing TIME	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	<u>28</u>		<u>121</u>		
10 min	<u>5</u>		<u>115</u>		
15 min	<u>0</u>		<u>114</u>		
20 min	<u>0</u>		<u>114</u>		
25 min	<u>0</u>		<u>114</u>		
30 min	<u>0</u>		<u>115</u>		

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow ✓

Surges

Down to Nothing

Nothing

Gas ✓

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Hard blow (blue gas first minute) - Next to light
blow at 20 min. lighter at 25 & 30 min
Blew Steady -

By

Production Forman
(Position)

Witness

Monica Tuckling
Schematic
Gas analysis on BH & Prod casing

E-mail address