

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

X ☒ Initial Report ☐ Final Report

Name of Company	Enervest Operating LLC	Contact	Lee Gardner
Address:	2700 Farmington Ave, Bld K, Suite #1 Farmington NM 87401	Telephone No.	505-325-0318
Facility Name:	State C C #001	Facility Type:	Oil/Gas Well

Surface Owner	Bud Schmitz	Mineral Owner	BLM	API No.	30-039-23884
---------------	-------------	---------------	-----	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	26	24N	1W					Rio Arriba

Latitude_N_36.279444 Longitude_W 106.909652

NATURE OF RELEASE

Type of Release	Condensate/ Produced Water	Volume of Release	100 BBL	Volume Recovered	20 BBL
Source of Release:	Frozen water drain valve	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	2-27-2014 2PM
Was Immediate Notice Given?	X <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Charlie Perrin		
By Whom?	Bill Julian	Date and Hour	2-26-2014 5:00 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes X <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	RCWD MAR 13 '14		

If a Watercourse was Impacted, Describe Fully.*



OIL CONS. DIV.
DIST. 3

Describe Cause of Problem and Remedial Action Taken.* The water drain valve frozen and cracked open allowing approximately 100 bbl. of condensate and produced water to leaking into the containment area. The free liquid was removed. The well was shut in.

Describe Area Affected and Cleanup Action Taken.*

The vacuum truck cleaned up any free liquids inside the containment wall. The six oil and water storage tanks will be removed. The impacted soil will be transported to T-N-T Land Farm. Soil samples will be submitted for laboratory analysis to confirm remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Wilbert L Gardner	Approved by Environmental Specialist: 		
Title: Sr. HSE Specialist	Approval Date:	Expiration Date:	
E-mail Address: Wgardner@enervest.net	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 3-12-2014	Phone: 505-325-0318		

* Attach Additional Sheets If Necessary

#Incident NCS 141065 3347