



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-28-14 Operator Burlington API #30-0 45-10271
Property Name Pierce SPC Well No. 2 Location: Unit 30 Township 31 Range 10
Well Status (Shut-In or Producing) Initial PSI: Tubing 143 Intermediate 0 Casing 268 Bradenhead 13

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing TIME	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
3:45 5 min	0	0	268	0	268
2:25 10 min	0	0	268	0	268
2:00 15 min	0	0	268	0	268
2:00 20 min	0	0	268		
2:00 25 min	0	0	268		
2:00 30 min	0	0	268		

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow	/	
Surges		
Down to Nothing		/
Nothing		DIST. 3
Gas		OIL CONS. DIV.
Gas & Water		RCVD APR 28 '14
Water	/	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 13

INTERMEDIATE 0

REMARKS:

Water flowed from start 1/4" stream
2nd puff when opened

By

Robert J. Black

Witness

M. Montenegro
Request water analysis on BH

(Position)

E-mail address _____