

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Company	Contact Crystal Tafoya
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9837
Facility Name: State E Gas Com 1E	Facility Type: Gas Well

Surface Owner BLM	Mineral Owner State (E-6515)	API No. 30-045-25145
--------------------------	-------------------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter A	Section 16	Township 29N	Range 10W	Feet from the 800	North/South Line North	Feet from the 800	East/West Line East	County San Juan
-------------------------	----------------------	------------------------	---------------------	-----------------------------	----------------------------------	-----------------------------	-------------------------------	---------------------------

Latitude 36.730999 Longitude -107.88400

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 30 BBLs	Volume Recovered 20 BBLs
Source of Release Pit Tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 1/30/2014 at 9:15AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM (Shari Ketcham) & NMOCD (Jonathan Kelly)	
By Whom? Lisa Hunter	Date and Hour 1/31/2014 at 1:28PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RCVD FEB 10 '14



OIL CONS. DIV.
DIST. 3

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.* Hole in pit tank discovered allowing 30bbls of produced water to be released. Water hauler contacted and recovered 20bbls of produced water. Well was immediately shut-in. This release was contained within the berm and did not leave location.

Describe Area Affected and Cleanup Action Taken.* ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Crystal Tafoya	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 4/28/14	Expiration Date:
E-mail Address: crystal.tafoya@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/6/2014 Phone: (505) 326-9837		

* Attach Additional Sheets If Necessary

NCS 141 185 6041