

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Energen Resources, Inc.	Contact: Ed Hasely
Address: 2010 Afton Place, Farmington, NM 87401	Telephone No: 505-324-4131
Facility Name: Davies Gas Com B #1E	Facility Type: Gas Well

Surface Owner: Federal	Mineral Owner: Federal	Lease No. NM-0309374
------------------------	------------------------	----------------------

LOCATION OF RELEASE API 30 045 26 272

Unit Letter I	Section 27	Township 28N	Range 13W	Feet from the 1850	North/South Line South	Feet from the 970	East/West Line East	County San Juan
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	--------------------

Latitude 36.63075 Longitude -108.200787

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 80 bbls	Volume Recovered: 80 bbls
Source of Release: Storage Tank	Date and Hour of Occurrence: 2/10/14	Date and Hour of Discovery: 2/10/14
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell - OCD Mark Kelly - BLM	
By Whom? Ed Hasely	Date and Hour: 2/10/14 at 2:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	



If a Watercourse was Impacted, Describe Fully.* NA

RCVD FEB 12 '14
OIL CONS. DIV.
DIST. 3

Describe Cause of Problem and Remedial Action Taken.* Due to miscommunication with the water trucking company, the produced water overflowed the storage tank into a lined berm. All fluids were contained in the lined berm. No fluid contacted the soil.

Describe Area Affected and Cleanup Action Taken.* The liquids were pulled from the lined berm using a water truck. All released fluids were recovered and properly disposed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ed Hasely	Approved by District Supervisor: 	
Title: Sr. Environmental Engineer	Approval Date: 4/28/14	Expiration Date:
E-mail Address: ed.hasely@energen.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/10/14 Phone: 505-324-4131 / 505-330-3584(cell)		

* Attach Additional Sheets If Necessary

#NCS 141 185 4984