



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

APR 30 2014

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 30-APR-2014 Operator BULLINGTON API #30-031-2128

Property Name SJ29-7 Well No. 112 Location: Unit _____ Section 29 Township 29 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing 163 Intermediate 101 Casing 166 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	1	101	175	1	181
10 min	1	102	177	1	181
15 min	1	104	180	1	181
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X
Nothing	X
Gas	X
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 1

REMARKS:

OPENED THE BRADEN HEAD NOTHING CAME OUT.
OPENED THE INTERMEDIATE AND IT BLEW DOWN
TO NOTHING IN 14 MINUTES. REQUESTED A GAS ANALYSIS

By Russ Hanes

Witness John Durham

(Position)

E-mail address _____