



(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/oed/District III/3distric.htm](http://emnrd.state.nm.us/oed/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

MAY 06 2014

Date of Test 5/6/2014 Operator West Largo API #30-045-28478

Property Name Crockett 25 Well No. 2 Location: Unit M Section 25 Township 29 Range 10

Well Status(Shut-In or Producing) Initial PSI: Tubing 6 Intermediate NA Casing 6 Bradenhead D

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	D	C	b		
10 min	O		b		
15 min	D		b		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

REMARKS:
No pressure on Bit

By John R. [Signature]

Witness Conrad D. Kelly

(Position)

E-mail address