

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report



Name of Company ConocoPhillips Company	Contact Lisa Hunter	
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9786	
Facility Name: San Juan 29-6 Unit 66	Facility Type: Gas Well	
Surface Owner Public (Private)	Mineral Owner Federal	API No. 3003907660

LOCATION OF RELEASE

Unit Letter K	Section 09	Township 29N	Range 06W	Feet from the 1450	North/South Line South	Feet from the 1850	East/West Line West	County Rio Arriba
-------------------------	----------------------	------------------------	---------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------------

Latitude **36.7368813** Longitude **-107.47039**

NATURE OF RELEASE

Type of Release Hydrocarbon/Condensate	Volume of Release 10 BBLs	Volume Recovered 0 BBLs
Source of Release Oil Production Tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 01/23/14 @ 2:00 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	RCVD FEB 5 '14
If a Watercourse was Impacted, Describe Fully.* N/A		OIL CONS. DIV. DIST. 3
Describe Cause of Problem and Remedial Action Taken.* Oil Production Tank developed a small leak due to corrosion on the weld seam at the bottom of tank. Well was shut in. Third-Party Environmental called to assess.		
Describe Area Affected and Cleanup Action Taken.* ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Lisa Hunter	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 5/5/14	Expiration Date:
E-mail Address: Lisa.Hunter@cop.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: February 3, 2014 Phone: (505) 326-9786		

* Attach Additional Sheets If Necessary

#NCS 141252 8489