



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrmd.state.nm.us/ocd/District 1.htm](http://emrmd.state.nm.us/ocd/District%201.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4/16/14 Operator El Pamco API #30-0 95-33079
Property Name Wilma May Well No. 1 Location: Unit F Section 30 Township 29N Range 10W
Well Status (Shut-In or Producing) Initial PSI: Tubing 2 Intermediate N/A Casing 5 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	N/A	5		
10 min	0	1	5		
15 min	0		5	N/A	
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X
Nothing	N/A
Gas	
Gas & Water	
Water	

OIL CONS. DIV DIST. 3
MAY 07 2014

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS:

By E. L. G.

(Position)

Witness _____

E-mail address _____