



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 13-MAY-2014 Operator LIVELY API #30-0 45-21074  
Property Name LIVELY Well No. 3 Location: Unit    Section 9 Township 29 Range 8  
Well Status(Shut-In or Producing) Initial PSI: Tubing 223 Intermediate 210 Casing 240 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min		210	240		240
10 min		210	240		240
15 min		210	240		240
20 min					240
25 min					240
30 min					240

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	X
Gas & Water	
Water	

RCVD MAY 13 '14

OIL CONS. DIV.

DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR    FRESH    SALTY    SULFUR    BLACK   

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 52

REMARKS: OPENED THE BRADENHEAD AND NOTHING CAME OUT  
OPENED THE INTERMEDIATE AND IT PRODUCED FOR THE ENTIRE TEST  
REQUESTED A GAS ANALYSIS AND A GAS STREAM

By Russell [Signature]  
Agent - Lucy BVP  
(Position)

Witness John [Signature]

E-mail address