



NEW MEXICO DEPT. OF NATURAL RESOURCES
2. NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX (505) 334-6170
<http://dnr.state.nm.us/ocd/District/OCDDistrict.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-16-2014 Operator ENERVEST OPERATING API #30-0 45-26970

Property Name PUMP CANYON Well No. SWD #1 Location: Unit J Section 7 Township 30N Range 8W

Well Status (Shut-In or Producing) Initial PSI: Tubing 1920 Intermediate Casing 6 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			FLOW CHARACTERISTICS	
	Bradenhead	INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg
5 min	0	/	6		
10 min	0	/	6		
15 min	0	/	6		
20 min					
25 min					
30 min					

Steady Flow

Surges

Down to Nothing

Nothing ✓

Gas

Gas & Water

Water

OIL CONS. DIV DIST. 3

MAY 07 2014

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD

INTERMEDIATE

REMARKS:

Injection well

By

Eth Payne
Pumper
(Position)

Witness

E-mail address