

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Burlington Resources, a Wholly Owned Subsidiary of ConocoPhillips Company	Contact Lisa Hunter
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9786
Facility Name: San Juan 29-7 #562	Facility Type: Gas Well

Surface Owner Public	Mineral Owner Fee	API No. 3003924904
-----------------------------	--------------------------	---------------------------

LOCATION OF RELEASE

Unit Letter B	Section 24	Township 29N	Range 07W	Feet from the 1105'	North/South Line North	Feet from the 1850'	East/West Line East	County Rio Arriba
-------------------------	----------------------	------------------------	---------------------	-------------------------------	----------------------------------	-------------------------------	-------------------------------	-----------------------------



Latitude 36.71563 Longitude -107.51915

NATURE OF RELEASE

Type of Release Produced Water (Coal Bed)	Volume of Release 12.7 BBLs	Volume Recovered 5 BBLs
Source of Release Water Tank (Leak)	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 01/20/14 @ 11:30 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		RCVD JAN 30 '14 OIL CONS. DIV. DIST. 3
Describe Cause of Problem and Remedial Action Taken.* Tank was leaking water out of two holes 15 feet from the bottom on a 20 feet tank. Pumping Unit stopped and tank contents pulled.		
Describe Area Affected and Cleanup Action Taken.* ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Lisa Hunter	Approval Date: 5/14/14	Expiration Date:
Title: Field Environmental Specialist	Conditions of Approval:	Attached <input type="checkbox"/>
E-mail Address: Lisa.Hunter@cop.com		
Date: January 28, 2014	Phone: (505) 326-9786	

* Attach Additional Sheets If Necessary

#NCS 141 343 0598