



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-15-14 Operator: Turner production Inc API #30-045-27063

Property Name: Riddle Florance Well No. 1 Location: Unit C Section 15 Township 30N Range 9W

Well Status(Shut-In or **Producing**) Initial PSI: Tubing 126 Intermediate NA Casing 126 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>NA</u>	<u>126</u>		
10 min	<u>0</u>	<u>NA</u>	<u>126</u>		
15 min	<u>0</u>	<u>NA</u>	<u>126</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing <u>X</u> puff	
Nothing	
Gas <u>X</u>	
Gas & Water	
Water	

OIL CONS. DIV DIST. 3

MAY 15 2014

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

By Glenn R Hise

Witness

 Operations Supervisor
(Position)

E-mail address ghise@mcclvain.com