

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BP America Production Company	Contact: Courtney Cochran
Address: 200 Energy Ct. Farmington, NM 87401	Telephone No.: 505-326-9457
Facility Name: Usselman GC 001	Facility Type: Natural Gas Well

Surface Owner: FEE	Mineral Owner: FEE	API No.: 3004511080
--------------------	--------------------	---------------------

LOCATION OF RELEASE

Unit Letter B	Section 04	Township 31N	Range 10W	Feet from the 1190	North/South Line North	Feet from the 1700	East/West Line East	County: San Juan
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	------------------

Latitude 36.9313 Longitude 107.8842

NATURE OF RELEASE

Type of Release: Natural Gas	Volume of Release: 868 MCF	Volume Recovered: none
Source of Release: dump valve	Date and Hour of Occurrence: 5/16/2014-5/21/2014	Date and Hour of Discovery: 5/21/2014
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Cory Smith – NMOCD & Shari Ketcham – BLM	
By Whom? Courtney Cochran – BP	Date and Hour: 5/28/2014 11:30 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

OIL CONS. DIV DIST. 3

MAY 30 2014

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Operations technician visiting location found compressor suction scrubber dump valve hung open and venting gas to the BGT. Shut in well and isolated compressor.

Describe Area Affected and Cleanup Action Taken.*

No clean-up action possible. Natural gas dissipated to the atmosphere.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.


OIL CONSERVATION DIVISION

Signature:



Printed Name: Courtney Cochran

Approved by Environmental Specialist:



Title: Environmental Advisor

Approval Date: 6/12/14

Expiration Date:

E-mail Address: Courtney.Cochran@bp.com

Conditions of Approval:

Attached ☐

Date: 5/28/2014 Phone: 505-486-2694

* Attach Additional Sheets If Necessary

#NCS 141 63 42 770