

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company <b>Burlington Resources Oil &amp; Gas Company</b>	Contact <b>Lindsay Dumas</b>
Address <b>3401 East 30<sup>th</sup> St, Farmington, NM</b>	Telephone No. <b>(505) 599-4089</b>
Facility Name: <b>Hanks 14E</b>	Facility Type: <b>Gas Well</b>

Surface Owner <b>BLM</b>	Mineral Owner <b>BLM (SF-077384)</b>	API No. <b>30-045-24479</b>
--------------------------	--------------------------------------	-----------------------------

#### LOCATION OF RELEASE

Unit Letter <b>O</b>	Section <b>12</b>	Township <b>27N</b>	Range <b>10W</b>	Feet from the <b>800</b>	North/South Line <b>FSL</b>	Feet from the <b>1530</b>	East/West Line <b>FEL</b>	County <b>San Juan</b>
-------------------------	----------------------	------------------------	---------------------	-----------------------------	--------------------------------	------------------------------	------------------------------	---------------------------

Latitude **36.58443** Longitude **-107.84271**

#### NATURE OF RELEASE

Type of Release <b>Natural Gas</b>	Volume of Release <b>313 MCF</b>	Volume Recovered <b>0 MCF</b>
Source of Release <b>Flow Line</b>	Date and Hour of Occurrence <b>5/17/2014 @ 1:00 pm</b>	Date and Hour of Discovery <b>5/22/2014 @ 3:00 PM</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**OIL CONS. DIV DIST. 3**  
**JUN 3 2014**

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

**Leak in flow line under ground between compressor discharge and inlet to meter run. The compressor was shut down and well was shut in. A one call was placed to replace flow line.**

Describe Area Affected and Cleanup Action Taken.\*

**No remediation necessary. Flow line was replaced; no contaminated soil was found when line was dug up.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature: *Lindsay Dumas*

Printed Name: **Lindsay Dumas**

Approved by Environmental Specialist:

Title: **Field Environmental Specialist**

Approval Date: **6/10/14**

Expiration Date:

E-mail Address: **Lindsay.Dumas@conocophillips.com**

Conditions of Approval:

Attached ☐

Date: **5/30/14**

Phone: **(505) 599-4089**

\* Attach Additional Sheets If Necessary

*#NOCB 141 6153403*

①