

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Burlington Resources Oil & Gas Company	Contact Crystal Tafoya
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9837
Facility Name: San Juan 32-9 Unit 271	Facility Type: Gas Well

Surface Owner Federal	Mineral Owner Federal (BLM -078513)	API No. 30-045-28031
------------------------------	--	-----------------------------

LOCATION OF RELEASE

Unit Letter K	Section 18	Township 32N	Range 9W	Feet from the 2120	North/South Line South	Feet from the 790	East/West Line West	County San Juan
-------------------------	----------------------	------------------------	--------------------	------------------------------	----------------------------------	-----------------------------	-------------------------------	---------------------------

Latitude **36.98267** Longitude **-107.8233**

NATURE OF RELEASE

Type of Release 2% KCL Water	Volume of Release 20 BBLS	Volume Recovered 0 BBLS
Source of Release Rig Pit	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 5/23/14 at 7:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
N/A

OIL CONS. DIV DIST. 3

MAY 30 2014



Describe Cause of Problem and Remedial Action Taken.*

The load valve on the rig pit was opened by an unknown person allowing 20bbbls of 2% KCL water to be released. The valve was quickly shut and the area immediately raked. The release remained on location and no volume was recovered.

Describe Area Affected and Cleanup Action Taken.*

ConocoPhillips will assess the soil to determine a path forward for clean-up if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Crystal Tafoya		Approved by Environmental Specialist: 	
Title: Field Environmental Specialist		Approval Date: 6/12/14	Expiration Date:
E-mail Address: crystal.tafoya@conocophillips.com		Conditions of Approval:	
Date: 5/29/2014 Phone: (505) 326-9837		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

#NCS 141 634 3060