

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office to  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company <b>Burlington Resources, a Wholly Owned Subsidiary of ConocoPhillips Company</b>	Contact <b>Lisa Hunter</b>
Address <b>3401 East 30<sup>th</sup> St, Farmington, NM</b>	Telephone No. <b>(505) 326-9786</b>
Facility Name: <b>Reese Mesa #8T</b>	Facility Type: <b>Natural Gas</b>

Surface Owner <b>BLM</b>	Mineral Owner <b>BLM</b>	API No. <b>3004533267</b>
--------------------------	--------------------------	---------------------------

**LOCATION OF RELEASE**

Unit Letter <b>E</b>	Section <b>12</b>	Township <b>32N</b>	Range <b>08W</b>	Feet from the <b>700</b>	North/South Line <b>North</b>	Feet from the <b>330</b>	East/West Line <b>West</b>	County <b>San Juan</b>
-------------------------	----------------------	------------------------	---------------------	-----------------------------	----------------------------------	-----------------------------	-------------------------------	---------------------------

Latitude 36.99799 Longitude -107.63243

**NATURE OF RELEASE**

Type of Release <b>Natural Gas</b>	Volume of Release <b>300 mcf</b>	Volume Recovered <b>0</b>
Source of Release <b>Blow out Preventer</b>	Date and Hour of Occurrence <b>06/03/14 @ 8:25 a.m.</b>	Date and Hour of Discovery <b>06/03/14 @ 8:25 a.m.</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*  
**While pulling pipe out of hole with wash pipe, the well "kicked" and wedged the wash pipe between Crown and Blow Out Preventer (BOP). BOP could not close and well vented until BOP was successfully closed, a total of 9.25 hours.**



Describe Area Affected and Cleanup Action Taken.\*  
**Internal investigation to prevent future occurrences is in progress. No further remediation necessary.**

**OIL CONS. DIV DIST. 3**

**JUN 10 2014**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature: 	Approved by Environmental Specialist: 	
Printed Name: <b>Lisa Hunter</b>	Approval Date: <b>6/12/14</b> Expiration Date:	
Title: <b>Field Environmental Specialist</b>	Conditions of Approval:	
E-mail Address: <b>Lisa.Hunter@cop.com</b>	Attached <input type="checkbox"/>	
Date: <b>June 6, 2014</b> Phone: <b>(505) 326-9786</b>		

\* Attach Additional Sheets If Necessary

#NCS 1416154023