



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6/17/2014 Operator COPC API #30-0 45-24316

Property Name Shepherd & Kelsey Well No. 1E Location: Unit D Section 29 Township 29 Range 11

Well Status(Shut-In or Producing) Initial PSI: Tubing 171 Intermediate — Casing 172 Bradenhead 3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	—	178		
10 min	0	—	181		
15 min	0	—	182		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	
Nothing		
Gas		
Gas & Water	✓	
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☒ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE —

REMARKS: Just a puff on bradenhead, at 4 mins. started gurgling
and ran out about 1 quart of water
Requested water sample

RCVD JUN 17 '14
OIL CONS. DIV.
DIST. 3

By Colton Mulee

Witness Paul Wain

MSO

(Position)

E-mail address —